



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	15 Jan 2023, 14:06:45
Transaction Number	66833618 (CC10006)	Queue Number	657315



Chassis Number	6T1BF9FK0FX566227
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Camry
Model Year	2015
Color	Silver
Mileage	659735 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Front Tyre	BOTH SIDE 2019/2021 CRACKED.	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2018 /2019 CRACKED ,LEFT DAMAGE.	الاطار الخلفي
02 Chassis Condition		الشاسي
02.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED.	الشاسيه
03 Interior Condition		الحاله الداخليه
03.A AC Condition	OK	المكيف
03.B Steering Wheel and control buttons	WORN OUT.	عجلة القيادة وازرار التحكم
03.C Door Panel	COVER LOOSE.	لوحة بطانة الباب
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION DAMAGE.	حالة المقاعد
05 Body		جسم المركبة
05.A Bumper	MISALIGN.	دعامية
05.B Paint	BODY PORTION REPAIRED ,REPAIRED,MINOR DENTS SRATCHES ON BODY.	الصبغ

DEFECT	REMARKS	
05.C Sign of front accident		وجود مؤشر لحادث في المقدمة
05.D Other	FRONT BUMPER FRAME ,FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED. SIGN OF TAXI.	اخرى
05.E Floor	PORTION DENT .	الارضية
05.F Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY.	صدأ
06 Engine Condition		المحرك
06.A Visual Engine Condition	REFITTED OIL LEAK ,ABNORMAL NOISY.	حالة المحرك النظرى
07 Transmission Condition		الجير
07.A Visual Gear Box Condition	REFITTED OIL LEAK .	حالة الجير النظرى
07.B Road Test	NOT CHECKED.	فحص علي الطريق
08 Suspension System		ممتص الصدمات
08.A Ball Joint	BOOT CUT .	مفصل كروي
08.B Arms	LOWER ARM BUSHES CRAKED.	ازرع
08.C Other	LINK ROD BALL JOINT WORN OUT .T	اخرى
09 Lights		الاضاءة
09.A Head Light	LENS FADED. LEFT SIDE LOW BEAM NOT WORKING.	الاضاءة الرئيسية
10 Wipers and Arms		المساحات
10.A Other	WATER TANK CAP MISSING.	اخرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.