

Queue Number

2643199

Transaction Date

14 Aug 2026, 16:39:03

Site Name

840 - Emirates Auctions

Transaction Number

53846186 (CC10021) (CC10011)



Vehicle Details

Chassis Number

SALLMAME4A*****

Specification

GCC Specification

Make

Range Rover

Model

Vogue

Model Year

2010

Color

White

Mileage

249484 Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY REPAINTED PORTION REPAIRED,EXCEPT ROOF,MINOR DENT SCRATCHES	الصبغ
01.B Doors	REAR LEFT SIDE REFITTED	أبواب
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Bumper	MISALIGN,GRILL LOOSE PORTION DAMAGED	دعامية
01.E Bonnet	REFITTED	غطاء المحرك

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	PARTS REFITTED GETTING RUSTY, OIL LEAK	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	FRONT SEAT COVER PORTION CRACK WORN OUT,BACK COVER PORTION LOOSE,RIGHT SEAT SIDE COVER PART MISSING	حالة المقاعد
---------------------	---	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	OIL LEAK MINOR JERKING PARTS REFITTED	الحالة النظرية للجير
05.B Propeller Shaft	REFITTED	ناقل الحركة
05.C DIFFERENTIAL	REFITTED	الدفرنشيل

Condition	Remarks	الحالة
05.D Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED,RIGHT SIDE BRACKET DAMAGED	الاضاءة الرئيسية
07.B Warning Light	WARNING MESSAGE ON DISPLAY	ضوء تحذير
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك و طنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Ball Joint	BOOT CUT	مفصل كروي
10 Interior Condition		الحالة الداخلية
10.A AC Condition	LOW COOLING,NOT WORKING PROPERLY,GRILL PORTION DAMAGED	المكيف
10.B Roof Light	COVER PART MISSING	أنارة السقف
10.C Audio	SCREEN FADED	صوتيات
10.D Dash Board	LEFT SIDE LOWER PORTION LOOSE LEATHER REFITTED	لوحة القيادة
10.E Roof Ceiling	LOOSE	بطانة السقف
10.F Sun Visor	RIGHT SIDE BRACKET DAMAGED	حاجب الشمس
10.G Odometer reading	DISPLAY GETTING FADED	قراءة عداد المسافات
10.H Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.I Steering Wheel and control buttons	GETTING WORN OUT	عجلة القيادة وازرار التحكم
10.J Sunroof	CURTAIN FABRIC LOOSE	فتحت سقف
10.K Gear Shifting Lever	KNOB GETTING WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on
wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae