





Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 27680636	Plate Category	: PRIVATE
Transaction Date	: 08 JUL 2021 14:12:31	Plate Number	: 830556 EA
Queue Number	: 365851	Import Doc. Ref.	:
Chassis Number	: 3N1CN7AP2CL830556	Manufacturer/Model	: NISSAN/VERSA
Engine Number	:	Model Year	: 2012
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.15 - Suspension Crack Or Bend, Bushes		التوصيلات
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
05 Body		الهيكل
05.02 - Paint		الصبغ
05.05 - Bumpers		الدعامية
05.07 - Floor		الارضية
05.08 - Chassis (Frame)		الشاصية
05.12 - Side Safety Frame		الواقبات الجانبية
06 General Items		الاشياء العامة
06.01 - Wiper Blades		ماسحات الزجاج الامامي
06.04 - Horn		الزامور
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.09 - Engine And Gear Box Performance Ok	OK	فحص حالة الماكينة والجير



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 27680636	Plate Category	: PRIVATE
Transaction Date	: 08 JUL 2021 14:12:31	Plate Number	: 830556 EA
Queue Number	: 365851	Import Doc. Ref.	:
Chassis Number	: 3N1CN7AP2CL830556	Manufacturer/Model	: NISSAN/VERSA
Engine Number	:	Model Year	: 2012
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

09.18 - A/C Not Cooling		عطل في المكيف
09.24 - Digital Display Damaged/Warning Lights	CHECK ENGINE & TPMS LIGHT ON	عطل في لوحة التحكم الالكتروني
09.25 - Body Repainted	BODY PORTIONS REPAINTED	أثر صيغ في المركبة
<p>The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.</p> <p style="text-align: right;">شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسؤولة عن العيوب الخفية</p>		

Test Certificate



Vehicle
Registration



X FAILED

Change possession :	65485810
Chassis No :	3N1CN7AP2CL830556
Vehicle Make :	NISSAN
Vehicle Model :	VERSA
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Black
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	241015 Kms.
Origin :	Mexico
Model Year :	2012
Gear Type :	--
Engine Size :	3500 CC
Engine No :	NIL
Horse Power :	109
Axles No :	2
Cylinders :	4
No Of Doors :	4
No Of Seats :	5
G. V. W. :	1420 Kgs.
Empty Weight :	1250 Kgs.

Certificate Number :	5-TAS-2021-14597105
Inspection Date :	11-07-2021
Certificate Print Date :	11-07-2021
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Emirates Auction
Total Time Taken :	16 min 46 sec
Appointment Ref Number :	--
Start Time :	15:12
End Time :	15:29
Lane :	01
Token No. :	13
Attempt :	1
Prints No :	1

Parameter Readings

Service brake imbalance on front axle	6 %	Service brake imbalance on rear axle	16 %	Parking brake imbalance between LHS and RHS	2 %	Vehicle on Petrol CO Reading	0.55 %
Vehicle on Petrol HC Reading	140 PPM VOL						

Inspection Findings

Defects	Issue	Severity
Battery fix battery bracket	Unsecure	Major
Dip beams(Low Beams) headlight fix both side head light bulb & wire connection	Missing	Major
Reflector Triangle	Not Available	Major

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	3500	1500	

Inspection Remarks:

MIDDLE REINFORCEMENT & FLOORING DENT /LOWER RADIATOR SUPPORT DENT / FRONT LEFT SIDE FRAME MEMBER END REPAIRED

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
59460	VTP Credit Account	14597105	AED 170 Collected on 11/07/2021
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Raul Canceran Galang

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسؤولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995

