

Queue Number 2920607

Transaction Date 29 Oct 2026, 16:47:01

Site Name
840 - Emirates AuctionsTransaction Number
81516109 (CC10013) (CC10019)

Vehicle Details

Chassis Number	W1NFF8GE1M*****
Specification	GCC Specification
Make	Mercedes
Model	GLS 580
Model Year	2021
Color	Black
Mileage	145321 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Paint	BODY MINOR DENT SCRATCHES	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR FULLY COVERED CHECK VISIBLE AREA ONLY	الارضية
01.D Bumper	MISALIGN	دعامية
01.E Bonnet	SHOCK NOT WORKING	غطاء المحرك

02 Chassis Condition الشاسي

02.A Chassis	CHASSIS FULLY COVERED CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Other	FOR FULL INSPECTION REMOVE INNER FENDER UNDER ENGINE FLOOR COVER FOR RECHECK	اخرى

03 Engine Condition المحرك

03.A Engine Visual Condition	VISUAL OK	الحالة النظرية للمحرك
------------------------------	-----------	-----------------------

04 Seats Condition المقاعد

04.A Seat Condition	REAR SEAT FOLDING NOT WORKING	حالة المقاعد
---------------------	-------------------------------	--------------

05 Transmission Condition الجير

05.A Gear Box Visual Condition	VISUAL OK	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR SCRATCHES	حالة الجنوط
07 Suspension System		ممتص الصدمات
07.A Arms	ARM BUSHES MINOR DRY CRACK	ازرع
08 Interior Condition		الحالة الداخلية
08.A AC Condition	OK, ADJUSTMENT PORTION MISSING	المكيف
08.B Sunroof	CURTAIN PORTION LOOSE	فتحت سقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae