



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>21 Apr 2022, 13:39:49</b>
Transaction Number	<b>51666284 (CC10008)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>1N4AA6APOGC380178</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Nissan</b>
Model	<b>Maxima</b>
Model Year	<b>2016</b>
Color	<b>Purple</b>
Mileage	<b>122296 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>USA Imported</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Doors	RIGHT SIDE BOTH REPAIRED, REPAINTED	أبواب
01.B Bumper	FRONT ASSMPY REFITTED	دعامية
01.C Floor	UNDE R FLOOR PARTS GETTING RUSTY	الارضية
01.D Paint	BODY PORTION REPAIRED REPAINTED ,MINOR DENTS SCRATCHES ON BODY	الصبغ
01.E Fenders	FRONT RIGHT SIDE REPLACED & REAR REPAIRED, REPAINTED	مدكار
<b>02 Engine Condition</b>		<b>المحرك</b>
02.A Visual Engine Condition	SIGN OF MINOR OIL LEAK	حالة المحرك النظري
<b>03 Transmission Condition</b>		<b>الجير</b>
03.A Road Test	NOT CHECKED	فحص علي الطريق
03.B Gear Box Mount	MOUNT RUBBER MINOR CRACKED	كرسي الجير
03.C Visual Gear Box Condition	OK	حالة الجير النظري
<b>04 Tires and Rims Condition</b>		<b>الاطارات</b>
04.A Front Tyre	BOTH SIDE 2018 WORN OUT	الاطار الامامي

DEFECT	REMARKS	
04.B Rear Tyre	BOTH SIDE 2018 WORN OUT	الاطار الخلفي
<b>05 Interior Condition</b>		<b>الحاله الداخليه</b>
05.A Air Bag	AIR BAG DAMAGED	وسائد هوائية
05.B Dash Board	LEATHER REPLACED	لوحة القيادة
<b>06 Chassis Condition</b>		<b>الشاصي</b>
06.A Chassis Extension	REAR RIGHT SIDE CHASSIS EXTENSSION DENT	تمديدات الشاسي
06.B Chassis	FRONT RIGHT SIDE CHASSIS MINOR BEND	الشاسيه
<b>07 Seats Condition</b>		<b>المقاعد</b>
07.A Seat Condition	DRIVER SEAT ADJUSTMENT NOISY	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



✓ PASS

Plate Details :	O 2684 Dubai Private		
Chassis No :	1N4AA6APOGC380178		
Vehicle Make :	NISSAN		
Vehicle Model :	MAXIMA		
Vehicle Class :	Light Vehicle		
Body Type :	SALOON		
Fuel :	Benzene		
Color :	Violet		
Drive Direction :	--		
Dimensions : (H x W x L) :	-- x -- x --		
Current Odometer :	122302 Kms.		
Origin :	United States	Model Year :	2016
Gear Type :	Automatic	Engine Size :	3500 CC
Engine No :	NIL	Horse Power :	300
Axles No :	2	Cylinders :	6
No Of Doors :	4	No Of Seats :	5
G. V. W. :	2268 Kgs.	Empty Weight :	1578 Kgs.

Certificate Number :	5-TAS-2022-16680339		
Inspection Date :	27-04-2022		
Certificate Print Date :	09-05-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	12 min 33 sec		
Appointment Ref Number :	--		
Start Time :	10:08	End Time :	10:21
Lane :	01	Token No. :	112
Attempt :	1	Prints No. :	2

## Carbon footprint



Thank you! You are environment protector

## Estimated Vehicle Consumption ( Rate in 12 Months )



7566 KM

Distance per  
year



779 L

Fuel consumed  
per year



1262 AED

Fuel cost per  
year



1.9 ton

Carbon footprint  
per year

## Parameter Readings

Service brake imbalance on  
front axle  
10 %

Service brake imbalance on  
rear axle  
11 %

Parking brake imbalance  
between LHS and RHS  
5 %

Vehicle on Petrol CO  
Reading  
0 %

Vehicle on Petrol HC  
Reading  
0 PPM VOL

## Inspection Remarks:

FRONT & REAR BUMPER / FRAME // FRONT RIGHT SIDE FENDER APRON WHEEL HOUSING REPAIRED // REAR RIGHT SIDE CRASH BOX DENT, MINOR ENGINE OIL LEAK, FRONT RIGHT SIDE AXLE BOOT LEAK, MIDDLE REINFORCEMENT MINOR DENT

## Payment Details

Inspection Performed by  
34439

Parking Slot No  
--

Payment Method  
Cash

Service Name  
Registration Test

Transaction Number  
16680339

Attempt  
1

Service Fees

AED 170 Collected on 27/04/2022

Received by

Sittu Paloth Sreesan Paloth

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتريخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية تريخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

