



### Test Certificate

|                     |                          |                    |           |
|---------------------|--------------------------|--------------------|-----------|
| Site Number         | : 840-TASJEEL EM AUCTION | Plate Code         | : 0       |
| Transaction Number  | : 18451787               | Plate Category     | : PRIVATE |
| Transaction Date    | : 04 NOV 2019 14:39:49   | Plate Number       | : 9020 EA |
| Queue Number        | : 115214                 | Import Doc. Ref.   | :         |
| Chassis Number      | : WBADU51077LE99020      | Manufacturer/Model | : BMW/Z4  |
| Engine Number       | :                        | Model Year         | : 2007    |
| Vehicle Class       | : LIGHT VEHICLE          | Vehicle Color      | : BLACK   |
| Service / Indicator | : DSC AUCTION            |                    |           |

#### Statement of Vehicle Condition

| Defect   | Result | Remarks                       |
|--|--------|-------------------------------|
| AUTOMATIC TEST:  |        |                               |
| 13 Brake System  |        | الفرامل                       |
| 13.04 - Brake Test   | Passed | فحص الفرامل                   |
| 14 Exhaust Gas Test  |        | الغاز العادم والكربون         |
| 14.01 - Exhaust Gas Test   | Passed | فحص الغاز العادم-الكربون      |
| VISUAL TEST:   |        |                               |
| 04 Tires Rims  |        | الاطارات والعجلات             |
| 04.01 - Front Left And Right Hands Tires                                   |        | الاطارات الامامية             |
| 04.07 - Rims   |        | الرنجات                       |
| 05 Body  |        | الهيكل                        |
| 05.02 - Paint  |        | الصبغ                         |
| 06 General Items   |        | الاشياء العامة                |
| 06.14 - Transmission Condition   |        | حالة ناقل الحركة              |
| 06.16 - Engine Condition, Smoke  |        | حالة المحرك - الدخان          |
| 07 Remarks   |        | ملاحظات                       |
| 07.04 - Others   |        | ملاحظات اخرى                  |
| 09 Auction   |        | الفحص الكامل                  |
| 09.02 - Need Wheel Alignment   |        | يحتاج الى ميزانية العجلات     |
| 09.06 - Chassis Ok   |        | الشاصي جيد                    |
| 09.24 - Digital Display Damaged/Warning Lights                             |        | عطل في لوحة التحكم الالكتروني |
| 09.25 - Body Repainted   |        | أثر صبغ في المركبة            |
| The Test Certificate Shows the test Result at the time of inspection only. |        |                               |