

Queue Number 2639700

Transaction Date 19 Aug 2026, 13:03:02

Site Name
840 - Emirates AuctionsTransaction Number
88388301 (CC10021) (CC10021)

Vehicle Details

Chassis Number JN6FE54S17*****
Specification GCC Specification
Make Nissan
Model Van
Model Year 2007
Color Yellow
Mileage N/A NA
Fuel Type Petrol
Transmission Type
No. Of Cylinders 4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY REPAINTED,PORION REPAIRED,MINOR DENTS SCRATCHES,PORION FADED RUSTY	الصيغ
01.B Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENT ,MUDDY,RUSTY	الارضية
01.D Bumper	MISALIGN,PORION DAMAGED	دعامية
01.E Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD INNER FENDER FRAME REPAIRED.	وجود مؤشر لحادث في المقدمة
01.F Vehicle Model	URVAN	طراز المركبة

02 Chassis Condition

الشاسي

02.A Chassis	FRONT LEFT SIDE CHASSIS END REPAIRED,CHASSIS GETTING RUSTY	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
---------------------	-----------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE CRACK,DAMAGED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE CRACK,DAMAGED	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك و طناوير الفرامل
09 Suspension System		ممتص الصدمات
09.A Leaf Spring	BUSHES CRACK	ازرع مفصل كروي عمود التوازن و مثبت عمود التوازن
09.B Arms	BUSHES CRACK	
09.C Ball Joint	BOOT CUT	
09.D Stabilizer Bar And Link Rod	BOOT CUT	
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY , (SIGN OF FLOODED)	اخرى
10.B AC Condition	NOT CHECK	المكيف
10.C Floor Matting	WORN OUT	فرش الأرضية
10.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.E Gear Shifting Lever	WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae