

05 Chassis Condition

06.A Floor

TEST CERTIFICATE

الشاصي

الارضية

Site Number **840-Emirates Auctions** Transaction Date 23 May 2023, 17:01:31

Transaction Number 51035000 (CC10010) Oueue Number 719207



Chassis Number JM7BM1SZ7F1300075

Engine Number

Vehicle Class Car Manufacturer Mazda

Model 3

Model Year 2015 Color

84969 Km Mileage

Fuel Type **Petrol**

No. Of Cylinders

Specification **GCC** Specification

REMARKS **DEFECT**

01 Transmission Condition الجير 01.A Road Test NOT CHECKED. فحص علي الطريق

01.B Visual Gear Box ОК حالة الجير النظرى Condition

02 Lights الاضاءة

02.A Head Light LENS FADED الاضاءة الرئيسية

03 Engine Condition المحرك

03.A Visual Engine Condition OK حالة المحرك النظرى

04 Brake Condition الفرامل

GETTING SPONGY. 04.A Brake Pedal دواسة الفرامل

05.A Chassis CHECKED VISIBLE AREA OK, الشاسيه

06 Body جسم المركبة

UNDER FLOOR FULLY COVERED.CHECKED ONLY VISIBLE

AREA. PORTION DENT. 06.B Vehicle Color WHITE. لون المركبة

| DEFECT | REMARKS | |
|--|---|------------------|
| 06.C Rusty | UNDER BODY ,SUSPENSION PARTS GETTING RUSTY | صدأ |
| 06.D Paint | DENTS SCRATCHES ON BODY. | الصبغ |
| 07 Interior Condition | | الحاله الداخليه |
| 07.A AC Condition | NO COOLING. | المكيف |
| 08 Suspension System | | ممتص الصدمات |
| | | • |
| 08.A Arms | LOWER ARM BUSHES CRACKED. | اندع |
| 08.A Arms 09 Tires and Rims Condition | LOWER ARM BUSHES CRACKED. | ازرع الاطارات |
| | LOWER ARM BUSHES CRACKED. BOTH SIDE 2014 EXPIRED ,CRACKED. | |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.