

Queue Number 2246247

Transaction Date 14 Mar 2026, 14:44:56

Site Name
840 - Emirates AuctionsTransaction Number
76733603 (CC10018) (CC10018)

Vehicle Details

Chassis Number	JN6BE6BS8E*****
Specification	GCC Specification
Make	Nissan
Model	Urvan
Model Year	2014
Color	White
Mileage	461428 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENT & SCRATCHES, PORTION FADED, PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	RUNNING BOARD DENT	الارضية
01.D Bumper	MISALIGN, PORTION DAMAGED	دعامية
01.E Fuel Tank	DENT	خزان الوقود

02 Chassis Condition الشاسي

02.A Chassis	CHASSIS MUDDY, GETTING RUSTY, CROSS MEMBER RUSTY, BULGED	الشاسيه
--------------	--	---------

03 Engine Condition المحرك

03.A Engine Visual Condition	ENGINE NOT START, ALL SYSTEM NOT CHECKED, REFITTED, OIL WET, PARTS GETTING RUSTY, OIL PAN DENT	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition المقاعد

04.A Seat Condition	COVER PORTION DAMAGED	حالة المقاعد
---------------------	-----------------------	--------------

05 Transmission Condition الجير

05.A Gear Box Visual Condition	NOT CHECKED, REFITTED, OIL WET, PARTS GETTING RUSTY	الحالة النظرية للجير
--------------------------------	---	----------------------

05.B DIFFERENTIAL	LEAK	الدفرنشل
-------------------	------	----------

Condition	Remarks	الحالة
05.C Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022, DRY CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022, DRY CRACKED	الاطار الخلفي
06.C Rims Condition	RUSTY	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
07.B Tail Light	RIGHT SIDE DAMAGED	الضوء الخلفي
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطناير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK	ممتص الصدمات
09.B Leaf Spring	BUSH CRACKED	مفصل كروي
09.C Ball Joint	BOOT CUT	
09.D Stabilizer Bar And Link Rod	BOOT CUT	
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
10.B AC Condition	NOT CHECKED	المكيف
10.C Floor Matting	PORTION DAMAGED	فرش الأرضية
10.D Door Panel	WORN OUT	لوحة بطانة الباب
10.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae

