





### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20538513	Plate Category	: PRIVATE
Transaction Date	: 09 AUG 2020 14:37:17	Plate Number	: 208283 EA
Queue Number	: 204578	Import Doc. Ref.	:
Chassis Number	: 3N1BC1C63DK208283	Manufacturer/Model	: NISSAN/TIIDA
Engine Number	:	Model Year	: 2013
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
01 Lights		الانوار
01.03 - Number Plate Lights		انوار لوحة الارقام
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.11 - Shock Absorbers		مخمد الصدمات
03 Brake System		نظام الفرامل
03.01 - Brake Efficiency Front Wheels Left And Right Hands		قوة فرامل المحور الامامي
03.05 - Brake Pedal		نواصة الفرامل
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
04.08 - Spare Tires		الاطار الاحتياطي
05 Body		الهيكل
05.04 - Fenders		المدكار
05.05 - Bumpers		الدعامية
05.08 - Chassis (Frame)		النشاصية
06 General Items		الاشياء العامة
06.14 - Transmission Condition		حالة ناقل الحركة
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
06.21 - Battery Condition		حالة البطارية
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
09 Auction		الفحص الكامل



### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20538513	Plate Category	: PRIVATE
Transaction Date	: 09 AUG 2020 14:37:17	Plate Number	: 208283 EA
Queue Number	: 204578	Import Doc. Ref.	:
Chassis Number	: 3N1BC1C63DK208283	Manufacturer/Model	: NISSAN/TIIDA
Engine Number	:	Model Year	: 2013
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
09.15 - Sign Of Rear Accident		أثر حادث في مؤخرة المركبة
09.18 - A/C Not Cooling	LOW COOLING	عطل في المكيف
09.25 - Body Repainted		أثر صيغ في المركبة
<p>The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.</p> <p>شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسئولة عن العيوب الخفية</p>		

# Test Certificate



173  
FAILED

Change possession :	64398658	
Chassis No :	3N1BC1C63DK208283	
Vehicle Make :	NISSAN	
Vehicle Model :	TIIDA	
Vehicle Class :	Light Vehicle	
Body Type :	HATCHBACK	
Fuel :	Benzene	
Color :	White	
Drive Direction :	--	
Dimensions : (H x W x L) -- x -- x --		
Current Odometer :	124480 Kms.	
Origin :	Mexico	Model Year :
Gear Type :	--	2013
Engine No :	MR1896998...	Engine Size :
Axles No :	2	3500 CC
No Of Doors :	5	Horse Power :
G. V. W. :	1650 Kgs.	123
		Cylinders :
		4
		No Of Seats :
		5
		Empty Weight :
		1250 Kgs.

Certificate Number :	5-TAS-2020-12320122	
Inspection Date :	11-08-2020	
Certificate Print Date :	11-08-2020	
Services :	Registration Test	
Vehicle Testing Partner :	Tasjeel	
Vehicle Testing Center :	Tasjeel Emirates Auction	
Total Time Taken :	7 min 53 sec	
Appointment Ref Number :	--	
Start Time :	11:42	End Time :
		11:50
Lane :	01	Token No. :
		4
Attempt :	1	Prints No. :
		1

## Parameter Readings

Service brake imbalance on front axle 8 %	Service brake imbalance on rear axle 13 %	Parking brake imbalance between LHS and RHS 25 %	Vehicle on Petrol CO Reading 0 %
Vehicle on Petrol HC Reading 33 PPM VOL			

## Inspection Findings

Defects	Issue	Severity
Tire change rear both side tires cracks & worn out	Cracked	Major
Warning triangle	Missing	Major

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	3500	1800	

## Inspection Remarks:

REAR LEFT CHASSIS END & BACK PANEL MINOR DENT /RIGHT SIDE RADIATOR FRAME/& APRON END REPAIRED/FENDER & BONNET REFITTED