



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **18 May 2023, 13:44:43**
 Transaction Number **90902677 (CC10013)** Queue Number **720962**



Chassis Number **JTEBU25J085149514**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Toyota**
 Model **Prado**
 Model Year **2008**
 Color **Maroon**
 Mileage **001 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **6**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Transmission Condition		الجير
01.A Visual Gear Box Condition	NOT CHECK	حالة الجير النظرى
01.B Road Test	NOT CHECK	فحص علي الطريق
02 Steering Condition		المقود
02.A Steering Boot	BOOT CUT	ربلة المقود
02.B Other	STABILIZER LINK BOOT CUT	اخرى
02.C Axle	BOOT CUT	اكسلات
02.D Tie Rod End	BOOT CUT	مؤخرة الرودادات
03 Engine Condition		المحرك
03.A Other	TOP COVER MISSING	اخرى
03.B Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK KEY MISSING OIL LEAK	حالة المحرك النظرى
03.C Mount	MOUNT RUBBER CRACK WEAK	كرسي
04 Interior Condition		الحاله الداخليه
04.A AC Condition	NOT CHECK	المكيف
04.B Mirror	LEFT SIDE VIEW MIRROR LOOSE	المرآيا

DEFECT	REMARKS	
04.C Odometer reading	NOT CHECK	قراءة عداد المسافات
04.D Dash Board	MELTED	لوحة القيادة
04.E Other	GEAR LEVER KNOB WORN OUT	اخرى
04.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

05 Lights**الاضاءة**

05.A Tail Light	LEFT SIDE PORTION CRACK	الانارة
05.B Head Light	LENS FADED ALL LIGHT NOT CHECK	الاضاءة الرئيسية

06 Suspension System**ممتص الصدمات**

06.A Shock Absorber	LEAK	ممتص الصدمات
06.B Ball Joint	BOOT CUT	مفصل كروي
06.C Arms	BUSH CRACK	ازرع

07 Body**جسم المركبة**

07.A Trunk	NOT OPEN FOR RECHCK	صندوق
07.B Fuel Tank	DENT	خزان الوقود
07.C Floor	UNDER FLOOR PORTION MUDDY DIRTY & GETTING RUSTY , CENTER CROSS MEMBER BOTH SUPPORT DENT	الارضية
07.D Bumper	MISALIGN SCRATCHES LIGHT PORTION CRACK	دعامية
07.E Paint	BODY PORTION REPAINTED PORTION REPAIRED PORTION FADED MINOR DENT SCRATCHES	الصبغ
07.F Roof	STRIP MISSING	السقف
07.G Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ

08 Tires and Rims Condition**الاطارات**

08.A Rims Condition	DENT SCRATCHES OUTER HUB COVER MISSING	حالة الجنوط
---------------------	--	-------------

09 Seats Condition**المقاعد**

09.A Seat Condition	PORTION CUT	حالة المقاعد
---------------------	-------------	--------------

10 Chassis Condition**الشاسي**

10.A Chassis	CHASSIS FRAME RUST PROOFED & PORTION GETTING RUSTY	الشاسيه
--------------	--	---------

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

