

TEST CERTIFICATE

Site Number Transaction Number **840-Emirates Auctions** 67826623 (CC10008)

Transaction Date

21 Apr 2022, 10:19:03

Oueue Number 312309

Car

Chassis Number

WBA7F0C54JGM23982

الصبغ

القوائم

Engine Number

Vehicle Class

Manufacturer **BMW**

Model **750LI**

2018 Model Year

Color Black

69005 Km Mileage

Fuel Type **Petrol**

No. Of Cylinders

Specification **USA** Imported



REMARKS

01 Body	جسم المركبة

01.A Fenders REAR BOTH SIDE REPAINTED, REPAIRED مدكار 01.B Trunk **AUTO NOT WORKING & REPAINTED , REFITTED** صندوق

01.C Paint BODY PORTION REPAINTED, PORTION REPAIRED, MINOR

DENT, SCRATCHES

01.D Floor UNDER FLOOR COVERD الارضية

01.E Sign of side accident وجود مؤشر لحادث في الجانب

01.F Pillars BOTH SIDE C/PILLAR, POST, WHEEL ARCH REPAIRED

02 Tires and Rims Condition الاطارات

02.A Front Tyre **BOTH SIDE 2020** الاطار الامامي **BOTH SIDE 2020** 02.B Rear Tyre الاطار الخلفى

03 Engine Condition المحرك

03.A Visual Engine Condition ОК حالة المحرك النظرى

04 Chassis Condition الشاصي

04.A Chassis REAR LEFT SIDE CHASSIS JOINT AREA MINOR DETACHED الشاسيه

05 Lights الاضاءة

DEFECT	REMARKS	
05.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
06 Transmission Condition		الجير
06.A Road Test	NOT CHECK	فحص علي الطريق
06.B Visual Gear Box	ОК	حالة الجير النظرى
Condition		3
07 Interior Condition		الحاله الداخليه
07.A AC Condition	ОК	المكيف
07.B Sunroof	NOT CLOSING	فتحت سقف
07.C Air Bag	DAMAGED	وسائد هوائية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate









VBA7F0C54JGM23982
BMW
750LI
Light Vehicle
SALOON
Benzene
Black
-xx
58997 Kms.
Model Year: 2018
Engine Size: 4400 CC
Horse Power:
Cylinders: 8
No Of Seats: 5
Empty Weight: 1200 Kgs.

Certificate Number: 1-TAS-2022-16582987 Inspection Date: 12-04-2022 Certificate Print Date : 12-04-2022 Services: Renewal Test Vehicle Testing Partner: Tasjeel Vehicle Testing Center: Tasjeel Al Qusais Total Time Taken: 9 min 3 sec Appointment Ref Number : --Start Time: 16:31 End Time: 16:40 Token No.: 460 Lane: Attempt: Prints No: 1 1

Carbon footprint



Keep protecting Dubai environment

Vehicle Consumption (last 12 Months)



Distance per

year

2678 L Fuel consumed per year 4339 AED

4339 AED Fuel cost per year

6.5 ton
Carbon footprint
per year

Parameter Readings

Service brake imbalance on front axle 3 %

Vehicle on Petrol HC
Reading
O PPM VOL

Service brake imbalance on rear axle 5 %

Service brake imbalance on between LHS and RHS 6 %

Parking brake imbalance between LHS and RHS 6 %

Reading 0 %

Inspection Remarks:

REAR BOTH DOOR PILLAR, LEFT QUARTER PANEL REPAIRED FRONT RIGHT SIDE MEMBER FRAME MINOR DENT(OLD)

Payment Details

Inspection Performed by
59452Payment MethodTransaction NumberService FeesParking Slot NoCash16582987AED 170 Collected on 12/04/2022--Renewal TestAttemptReceived byShaima majid

- 1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.
 تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية
 ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال
 30. يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.