CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2958557
Transaction Date	09 Nov 2026, 13:03:01
Site Name	840 - Emirates Auctions
Transaction Number	48281732 (CC10009) (CC10011)



Vehicle Details

Chassis Number	JN1CV7AP0G*******
Specification	GCC Specification
Make	Infiniti
Model	Q50
Model Year	2016
Color	Grey
Mileage	155323 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	LEFT SIDE BOTH REPAINTED PORTION REPAIRED,RIGHT SIDE BOTH REPAIRED REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION FADED	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED PORTION REPAITRED,FRONT REFITTED	أبواب
01.D Rusty	UNDER BODYPARTS SUSPENSION GETTING RUSTY	صدأ
01.E Floor	FLOOR MUDDY PORTION DENT	الارضية
01.F Bumper	MISALIGN,SIGN OF CRACK	دعامية
01.G Roof	REPAINTED	السقف
01.H Bonnet	REPAINTED PORTION REPAIRED	غطاء المحرك
01.I Trunk	REFITTED,REAR SWITCH WORN OUT	صندوق
01.J Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	FRONT CHASSIS FULLY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	STEAM WASH REMOVE ALL UNDER COVERS FOR RECHECK PROPERLY	اخري
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL WET PARTS REFITTED GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY MINOR JERKING	الحالة النظريه للجير
05.B Road Test	MOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACKED	الاطار الخلفي
06.C Rims Condition	MINOR DENTS SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Tail Light	PORTION CRACK	الضوء الخلفي
07.C Indicator & Hazard light	BOTH SIDE MIRROR INDICATOR LIGHT COVER PORTION CRACK	الاشارات
07.D Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACKED LEFT SIDE BRACKET BEND	ازرع
09 Interior Condition		الحاله الداخليه
09.A Other	CUP HOLDER PANEL PORTION WORN OUT	اخري
09.B AC Condition	OK	المكيف
09.C Audio	DISPLAY GETTING FADED,TOUCH LCD FADED	صوتيات
09.D Dash Board	PORTION MELTED	لوحة القياده
09.E Sun Visor	LEFT SIDE MINOR LOOSE	حاجب الشمس
09.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
09.H Engine Start Button	GETTING WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.