

Queue Number 2845217

Transaction Date 13 Oct 2026, 08:08:45

Site Name
840 - Emirates AuctionsTransaction Number
74912751 (CC10021) (CC10019)

Vehicle Details

Chassis Number KNCTB241X5*****
 Specification GCC Specification
 Make Kia
 Model Prego
 Model Year 2005
 Color White
 Mileage N/A NA
 Fuel Type Diesel
 Transmission Type
 No. Of Cylinders 4

Condition	Remarks	الحالة
-----------	---------	--------

01 Body	جسم المركبة
---------	-------------

01.A Paint	BODY REPAINTED PORTION REPAIRED ,MINOR DENTS SCRATCHES ,PORTION RUSTY PORTION FADED .	الصبغ
01.B Floor	UNDER FLOOR,SUSPENSION NOT CHECK	الارضية
01.C Bumper	MISALIGN PORTION DAMAGED.	دعامية
01.D Windshield	FRONT CRACKED	زجاج
01.E Roof	PORTION RUSTY HOLE	السقف
01.F Bonnet	PORTION RUSTY HOLE	غطاء المحرك
01.G Other	(VISUAL INSPECTION ONLY)	اخرى

02 Chassis Condition	الشاسي
----------------------	--------

02.A Chassis	NOT CHECKED	الشاسيه
--------------	-------------	---------

03 Engine Condition	المحرك
---------------------	--------

03.A Engine Visual Condition	ENGINE NOT START ALL SYSTEM NOT CHECK	الحالة النظرية للمحرك
------------------------------	---------------------------------------	-----------------------

04 Seats Condition	المقاعد
--------------------	---------

04.A Seat Condition	PORTION CRACKED & REAR MISSING	حالة المقاعد
---------------------	--------------------------------	--------------

05 Transmission Condition	الجير
---------------------------	-------

05.A Gear Box Visual Condition	NOT CHECKED	الحالة النظرية للجير
--------------------------------	-------------	----------------------

Condition	Remarks	الحالة
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE CRACKED DAMAGED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE CRACKED DAMAGED	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED,ALL LIGHT NOT CHECKED .	الاضاءة الرئيسية
08 Interior Condition		الحاله الداخليه
08.A Other	INTERIOR PARTS RUSTY WATER FLOODED	اخرى
08.B AC Condition	NOT CHECKED	المكيف
08.C Dash Board	PORTION DAMAGED,CRACKED	لوحة القيادة
08.D Roof Ceiling	LOOSE	بطانه السقف
08.E Odometer reading	NOT CHECKED	قراءة عداد المسافات
08.F Door Panel	PORTION CRACKED	لوحة بطانة الباب
08.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae