CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2906608
Transaction Date	26 Oct 2026, 15:55:01
Site Name	840 - Emirates Auctions
Transaction Number	51350566 (CC10021) (CC10021)



Vehicle Details

Chassis Number	3N1AB7AP6E*******
Specification	Imported
Make	Nissan
Model	Sentra
Model Year	2014
Color	Red
Mileage	N/A Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN , PORTION DAMAGE	دعامية
01.E Sign of front accident	BUMPER FRAME, BULKHEAD, RADIATOR SUPPORT, FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة
01.F Sign of back accident	BACK PANEL, QUATER PANEL, COMPARTMENT REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	FRONT BOTH SIDE CHASSIS BADLY REPAIRED & REAR BOTH SIDE CHASSIS EXTENSION END , BEND	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED MINOR OIL LEAK . PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	NOT CHECKED REFITTED MINOR OIL LEAK PARTS RUSTY	الحالة النظريه للجير
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
06.B Tail Light	REFLECTOR MISSING	الضوء الخلفي
07 Interior Condition		الحاله الداخليه
07.A Other	CENTER CONSOLE BOX COVER WORN OUT , INETRIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
07.B Mirror	CENTER VIEW MIRROR FADED & FRONT BOTH SIDE VIEW MIRROR OUTER PANEL COVER MISSING	المرايا
07.C AC Condition	NOT CHECK	المكيف
07.D Roof Light	SHADE POCKET DAMAGE	أنارة السقف
07.E Dash Board	PORTION WORN OUT	لوحة القياده
07.F Roof Ceiling	PORTION WORN OUT	بطانه السقف
07.G Sun Visor	LEFT SIDE DAMAGE	حاجب الشمس
07.H Door Panel	PORTION WORN OUT	لوحة بطانة الباب
07.I Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
07.J Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae