

Queue Number	2521707	Transaction Date	09 Jul 2026, 11:27:40
Site Name	840 - Emirates Auctions	Transaction Number	97955564 (CC10006) (CC10006)
		Vehicle Details	
		Chassis Number	JTHBK1GG9D*****
		Specification	GCC Specification
		Make	Lexus
		Model	ES 350
		Model Year	2013
		Color	White
		Mileage	171186 Km
		Fuel Type	Petrol
		Transmission Type	
		No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY REPAINTED, PORTION REPAIRED, MINOR DENT & SCRATCHES, PORTION FADED, PORTION RUSTY, SIGN OF HAIL STORM.	الصبغ
01.B Rusty	UNDER BODY PARTS, SUSPENTION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION COVER, MUDDY, PORTION RUSTY	الارضية
01.D Windshield	FRONT & REAR DAMAGED	زجاج
02 Chassis Condition		الشاسي
02.A Chassis	COVERD, CHECKED VISIBLE AREA ONLY OK	الشاسيه
03 Engine Condition		المحرك
03.A Mount	BUSH CRACKED	كرسي
03.B Engine Visual Condition	ENGINE NOT START, ELECTRIC ISSUE ALL SYSTEM NOT CHECKED, REFITTED, OIL WET, PARTS RUSTY	الحالة النظرية للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	NOT CHECKED, REFITTED, OIL WET, PARTS RUSTY	الحالة النظرية للجير
04.B Gear Box Mount	BUSH CRACKED	كرسي الجير
04.C Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات

Condition	Remarks	الحالة
05.A Front Tyre	BOTH SIDE 2016 EXPIRED, CRACKED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2016 EXPIRED, CRACKED	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADED, COVER CRACKED	الاضاءة الرئيسية
06.B Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	LEAK	ممتص الصدمات
07.B Arms	BUSHES CUT	ازرع
07.C Ball Joint	BOOT CUT	مفصل كروي
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR PARTS GETTING RUSTY, WATER FLOODED	اخرى
08.B AC Condition	NOT CHECK	المكيف
08.C Power Window Switch And Glass	NOT CHECK	مفتاح النافذه و الزجاج
08.D Floor Matting	MUDDY, PORTION DAMAGED	فرش الأرضيه

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae