CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2906091
Transaction Date	31 Oct 2026, 09:33:58
Site Name	840 - Emirates Auctions
Transaction Number	28645816 (CC10010) (CC10010)



Vehicle Details

Chassis Number	*******UP1*******
Specification	Imported
Make	Toyota
Model	Vios
Model Year	2005
Color	Silver
Mileage	177702 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	BOTH SIDE REFITTED REPAINTED .,	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Doors	LEFT SIDE REPAINTED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.F Bumper	MISALIGN ,SCRATCHES . PORTION DAMAGED.	دعامية
01.G Bonnet	REPAINTED	غطاء المحرك
02 Chassis Condition		الشاصي
02.A Chassis	FRONT CHASSIS END DENT .	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION CUT .	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير

Condition	Remarks	الحالة
05.B Road Test	NOT CHECKED.	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACKED.	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACKED.	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES,HUB COVER MISSING	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07.B Tail Light	BROKEN DAMAGED.	الضوء الخلفي
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY .	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK.	ممتص الصدمات
09.B Arms	BUSHES CRACKED.	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
11.B AC Condition	NOT CHECKED .	المكيف
11.C Dash Board	PORTION LOOSE.	لوحة القياده
11.D Roof Ceiling	LEFT SIDE PILLAR COVER LOOSE.	بطانه السقف
11.E Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
11.F Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
11.G Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.