



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>18 Jul 2022, 14:54:03</b>
Transaction Number	<b>54594525 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>JN1BC13D56T010215</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Nissan</b>
Model	<b>Tiida</b>
Model Year	<b>2006</b>
Color	<b>Gold</b>
Mileage	<b>220787 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A Dash Board	DASH BOARD PORTION DAMAGED & CONSOLE BOX COVER DAMAGED	لوحة القيادة
01.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
01.C Odometer reading	NOT CHECK	قراءة عداد المسافات
01.D AC Condition	NOT CHECK	المكيف
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Other	FRONT FENDER FRAME , RADITOR SUPPORT, BUMPER FRAME ,BULK HEAD REPAIRED & LOWER SUPPORT DAMAGED	اخرى
02.B Bumper	PORTION DAMAGED & MISALIGN	دعامية
02.C Trunk	DEEP DENT	صندوق
02.D Paint	BODY TOTALY,REPAINTED,PORTION REPAIRED EXCEPT ROOF,MINOR DENTS, SCRATCHES , PORTION RUSTY, FADED	الصبغ
02.E Windshield	FRONT CRACKED	زجاج
02.F Sign of back accident		وجود مؤشر لحادث في الخلف
02.G Sign of front accident		وجود مؤشر لحادث في المقدمة

DEFECT	REMARKS	
02.H Rusty	UNDER BODY PARTS, SUSPENSION ,FLOOR GETTING MINOR RUSTY	صدأ
02.I Paint	BODY TOTALY,REPAINTED,PORTION REPAIRED EXCEPT ROOF,MINOR DENTS, SCRATCHES , PORTION RUSTY, FADED	الصبغ
<b>03 Lights</b>		<b>الاضاءة</b>
03.A Head Light	LENS FADED	الاضاءة الرئيسية
03.B Other	ALL LIGHTS NOT CHECK	اخرى
03.C Tail Light	LEFT SIDE LOOSE	الانارة
<b>04 Suspension System</b>		<b>ممتص الصدمات</b>
04.A Arms	LOWER ARM BUSHES CRACKED	ازرع
04.B Ball Joint	BOOT CUT	مفصل كروي
<b>05 Tires and Rims Condition</b>		<b>الاطارات</b>
05.A Front Tyre	BOTH SIDE 2016, EXPIRED CRACKED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2016, EXPIRED CRACKED	الاطار الخلفي
<b>06 Chassis Condition</b>		<b>الشاسي</b>
06.A Chassis	REAR BOTH SIDE CHASSIS EXTENSION REPAIRED	الشاسيه
<b>07 Engine Condition</b>		<b>المحرك</b>
07.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK & OIL LEAK & REFITTED	حالة المحرك النظري
07.B Mount	BUSHES CRACKED	كرسي
<b>08 Transmission Condition</b>		<b>الجير</b>
08.A Road Test	NOT CHECK	فحص علي الطريق
08.B Visual Gear Box Condition	REFITTED & NOT CHECK	حالة الجير النظري
<b>09 Seats Condition</b>		<b>المقاعد</b>
09.A Seat Condition	PORTION DAMAGED	حالة المقاعد
<b>10 Steering Condition</b>		<b>المقود</b>
10.A Tie Rod End	BOOT CUT	مؤخرة الرودادات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

