



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	16 Jan 2022, 17:51:45
Transaction Number	91260347 (CC10006)	Queue Number	312309



Chassis Number	1GNWKLEG2DR184894
Engine Number	
Vehicle Class	Car
Manufacturer	Chevrolet
Model	Suburban
Model Year	2013
Color	Grey
Mileage	107777 Miles
Fuel Type	Petrol
No. Of Cylinders	8
Specification	USA Imported

DEFECT	REMARKS	
01 Lights		الاضاءة
01.A Head Light	OK	الاضاءة الرئيسية
01.B Tail Light	OK	الانارة
02 Wipers and Arms		المساحات
02.A Wiper Arm & Blade	WORN OUT	ازرع المساحات والشفرات
03 Interior Condition		الحالة الداخليه
03.A Door Panel	FRONT LEFT SIDE LOOSE	لوحة بطانة الباب
03.B AC Condition	OK	المكيف
03.C Mirror	OK	المرايا
04 Body		جسم المركبة
04.A Bumper	REPAINTED	دعامية
04.B Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
04.C Rusty	UNDER BODY PARTS, SUSPENSION , CHASSIS GETTING RUSTY	صدأ
04.D Bonnet	PORTION REPAIRED & REPAINTED	غطاء المحرك
04.E Fenders	FRONT LEFT SIDE PORTION REPAIRED, REPAINTED & RIGHT	مدكار

DEFECT	REMARKS	
	SIDE REPAINTED	
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
06 Transmission Condition		الجير
06.A Gear Box	REFITTED	الجير
06.B Road Test	NOT CHECK	فحص علي الطريق
07 Chassis Condition		الشاصي
07.A Chassis	CHASSIS FRAME COMPLETELY RUST PROOFED & RUSTY	الشاسيه
08 Steering Condition		المقود
08.A Tie Rod End	BUSHES CUT	مؤخرة الرودادات
09 Suspension System		ممتص الصدمات
09.A Ball Joint	BUSHES CUT	مفصل كروي
09.B Other	STABILIZER LINK BUSHES DRY CRACKED	اخرى
09.C Shock Absorber	FRONT LEAK	ممتص الصدمات
09.D Leaf Spring	REAR LEAF SPRING BUSHES CRACKED	
10 Engine Condition		المحرك
10.A Engine Condition	OK	حالة المحرك
11 Seats Condition		المقاعد
11.A Seat Condition	OK	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.