



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>27 Nov 2022, 16:47:45</b>
Transaction Number	<b>73955093 (CC10006)</b>	Queue Number	<b>631000</b>



Chassis Number	<b>sallsaad4ca747931</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Range Rover</b>
Model	<b>Sport</b>
Model Year	<b>2012</b>
Color	<b>Black</b>
Mileage	<b>144719 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	FRONT LEFT SIDE PORTION REPAINTED & FRONT RIGHT SIDE PORTION REPAIRED,REPAINTED & REFITTED & REAR RIGHT SIDE REPAINTED	مدكار
01.B Bonnet	REPLACED	غطاء المحرك
01.C Other	FRONT BUMPER FRAME BULK HEAD , FENDER FRAME REPAIRED	اخرى
01.D Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT SCRATCHES	الصبغ
01.E Rusty	UNDER BODY PARTS, SUSPENTION GETTING RUSTY	صدأ
01.F Sign of front accident		وجود مؤشر لحادث في المقدمة
<b>02 Interior Condition</b>		<b>الحالة الداخلية</b>
02.A AC Condition	OK	المكيف
02.B Roof Ceiling	LOOSE	بطانه السقف
02.C Mirror	RIGHT SIDE ADJUSTMENT NOT WORKING PROPERLY	المرآيا
02.D Roof Light	NOT WORKING PROPERLY & LOOSE	أنارة السقف
02.E Dash Board	WORN OUT	لوحة القيادة
02.F Sunroof	NOT WORKING	فتحت سقف
02.G Sun Visor	LIGHT NOT WORKING	حاجب الشمس

DEFECT	REMARKS	
<b>03 Transmission Condition</b>		<b>الجير</b>
03.A Visual Gear Box Condition	OIL LEAK & REFITTED	حالة الجير النظرى
03.B DIFFERENTIAL	REFITTED, OIL LEAK	الدفرنشيل
03.C Propeller Shaft	REFITTED	ناقل الحركة
03.D Road Test	NOT CHECK	فحص علي الطريق
03.E Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
<b>04 Tires and Rims Condition</b>		<b>الاطارات</b>
04.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
04.B Rims Condition	RIMS HAVE MINOR SCRATCHES	حالة الجنوط
04.C Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
<b>05 Steering Condition</b>		<b>المقود</b>
05.A Rack Pinion	OIL LEAK	مسطرة المقود
<b>06 Chassis Condition</b>		<b>الشاصي</b>
06.A Chassis	OK	الشاسيه
<b>07 Engine Condition</b>		<b>المحرك</b>
07.A Visual Engine Condition	OIL LEAK & REFITTED, ABNORMAL NOISY	حالة المحرك النظرى
<b>08 Lights</b>		<b>الاضاءة</b>
08.A Warning Light	WARNING MESSAGE	ضوء تحذير

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.