



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	19 May 2022, 16:59:41
Transaction Number	24384476 (CC10008)	Queue Number	312309



Chassis Number	WBABD51055PK28581
Engine Number	
Vehicle Class	Car
Manufacturer	BMW
Model	330
Model Year	2005
Color	Black
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Front Tyre	BOTH SIDE 2017 EXPIRED , CRACKED	الاطار الامامي
01.B Rear Tyre	2017.2016 EXPIRED CRACKED	الاطار الخلفي
02 Body		جسم المركبة
02.A Paint	BODY REPAINTED PORTION REPAIRED , MINOR DENTS SCRATCHES ON BODY	الصبغ
02.B Fenders	REPAINTED PORTION REPAIRED , FRONT REFITTED	مدكار
02.C Doors	RIGHT SIDE DOOR REPAINTED , PORTION REPAIRED	أبواب
02.D Trunk	REPAIRED REPAINTED	صندوق
02.E Bonnet	REPAINTED SHOCK WEAK	غطاء المحرك
02.F Bumper	FRONT RIGHT SIDE GRILL MISSING, BUMPER MISALIGN	دعامية
02.G Floor	FLOOR CHASSIS FRAME RUST PROOFED , FLOOR HAVE DENT & HOLE	الارضية
03 Engine Condition		المحرك
03.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK & OIL LEAK, REFITTED	حالة المحرك النظري
03.B Mount	MOUNT RUBBER CRACKED	كرسي

DEFECT	REMARKS	
04 Transmission Condition		الجير
04.A Road Test	NOT CHECKED	فحص علي الطريق
04.B Visual Gear Box Condition	OIL LEAK REFITTED	حالة الجير النظرى
04.C Gear Box Mount	MOUNT RUBER CRACKED	كرسي الجير
05 Interior Condition		الحاله الداخليه
05.A AC Condition	NOT CHECKED	المكيف
05.B Mirror	LEFT SIDE GLASS DAMAGED	المرايا
05.C Odometer reading	NOT CHECKED	قراءة عداد المسافات
06 Chassis Condition		الشاصي
06.A Chassis	OK	الشاسيه
07 Suspension System		ممتص الصدمات
07.A Arms	BOTH SIDE LOWER ARM BUSHES CRACKED	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
07.C Shock Absorber	LEAK	ممتص الصدمات
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CUT	مؤخرة الروداد
08.B Steering Oil	OIL LEAK	زيت المقود
08.C Steering Boot	BOOT CUT	ربلة المقود
09 Seats Condition		المقاعد
09.A Seat Condition	COVERS DAMAGED	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.