

Queue Number 2822649

Transaction Date 01 Oct 2026, 14:24:40

Site Name
840 - Emirates AuctionsTransaction Number
87268120 (CC10010) (CC10010)

Vehicle Details

Chassis Number	WBAGN61024*****
Specification	GCC Specification
Make	BMW
Model	745LI
Model Year	2004
Color	Black
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.D Bumper	MISALIGN PORTION DAMAGED	دعامية
01.E Windshield	REAR CRACKED .	زجاج
01.F Trunk	NOT OPEN.	صندوق
01.G Sign of front accident	FRONT ASSEMBLY REFITTED.	وجود مؤشر لحادث في المقدمة
01.H Sign of side accident		وجود مؤشر لحادث في الجانب
01.I Sign of back accident	BACK PANEL DENT.	وجود مؤشر لحادث في الخلف

02 Chassis Condition الشاسي

02.A Chassis	CHASSIS COMPLETE COVERED OILY MUDDY ,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
02.B Other	CLEAN STEAM WASH CHASSIS FOR RECHECK .	اخرى

03 Engine Condition المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY,COOLANT MIXED.	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	DIRTY LOOSE PORTION CUT . PORTION DAMAGED .	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED ..	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE EXPIRED CRACKED WORN OUT .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE EXPIRED CRACKED WORN OUT .	الاطار الخلفي
06.C Rims Condition	MINOR DENTS SCRATCHES .	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	WEAK .BODY LEVEL LOW.	ممتص الصدمات
09.B Arms	BUSHES CUT .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY , (SIGN OF FLOODED)	اخرى
11.B Mirror	LOOSE.	المرايا
11.C AC Condition	NOT CHECKED ,GRILL PORTION LOOSE.	المكيف
11.D Floor Matting	CENTER CONSOLE BOX DAMAGED .	فرش الأرضيه
11.E Dash Board	PORTION LOOSE.	لوحة القيادة
11.F Roof Ceiling	PORTION LOOSE.	بطانه السقف
11.G Sun Visor	LOOSE.	حاجب الشمس
11.H Odometer reading	NOT CHECKED .	قراءة عداد المسافات
11.I Door Panel	WORN OUT LOOSE . FADED.	لوحة بطانة الباب
11.J Steering Wheel and control buttons	WORN OUT LOOSE.	عجلة القيادة وازرار التحكم
11.K Gear Shifting Lever	KNOB LOOSE . WORN OUT .	ذراع نقل السرعات
12 Engine Cooling System		نظام تبريد المحرك
12.A Coolant tank	OIL MIXED WITH COOLANT.	خزان التبريد



[link: carcheck.ae/certificate](https://carcheck.ae/certificate)carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae