

Queue Number

2844202

Transaction Date

07 Oct 2026, 13:19:15

Site Name

840 - Emirates Auctions

Transaction Number

70407139 (CC10010) (CC10010)



Vehicle Details

Chassis Number	JTNBZ4HK9K*****
Specification	GCC Specification
Make	Toyota
Model	Camry
Model Year	2019
Color	White
Mileage	155243 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REFITTED.	مذكّر
01.B Paint	BODY REPAINTED ,ACCEPT ROOF ,PORTION REPAIRED MINOR DENTS SCRATCHES PORTION RUSTY FADED.	الصبغ
01.C Doors	FRONT LEFT ,REAR RIGHT REFITTED .	أبواب
01.D Rusty	UNDER BODY PARTS, SUSPENTION GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR CHASSIS COMPLETE COVERED ,PORTION DENT . CHECKD ONLY VISIBLE AREA .	الارضية
01.F Bumper	MISALIGN,PORTION DAMAGED . SCRATCHES .	دعامية
01.G Windshield	FRONT CHANGED .	زجاج
01.H Bonnet	REFITTED .	غطاء المحرك
01.I Pillars	LEFTSIDE A/RIGHT SIDE B/C PILLARS ROCKER PANEL REPAIRED.	القوائم
01.J Sign of front accident	FRONT BULKHEAD ,RADIATOR SUPPORT ,CROSS MEMBER DENT .	وجود مؤشر لحادث في المقدمة
01.K Sign of side accident	QUARTER PANEL ,WHEEL ARCH REPAIRED.	وجود مؤشر لحادث في الجانب

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETE COVERED ,PORTION MUDDY ,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
02.B Other	REMOVE FENDER COVER UNDER COVER FOR INSPECTION .	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL WET COMPONENT PARTS RUSTY ABNORMAL NOIST SHAKING ,MISFIRING.	الحالة النظرية للمحرك
------------------------------	--	-----------------------

Condition	Remarks	الحالة
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	COMPONENT PARTS RUSTY GET JERKING.	الحالة النظرية للجير
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024 CRACKED WORN OUT .	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024 CRACKED WORN OUT.	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS GETTING FADED.	الاضاءة الرئيسية
06.B Warning Light	EXTRA WARNING LIGHT /MESSAGE ON IN CLUSTER.	ضوء تحذير
07 Brake Condition		الفرامل
07.A Brake Pedal	GETTING SPONGY.	دواسة الفرامل
07.B Disc&Drum	PARTS RUSTY.	دسك وطمناير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	MINOR LEAK WEAK .	ممتص الصدمات
08.B Arms	BUSHES CRACKED .	ازرع
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS GETTING RUSTY,SIGN OF FLOODED	اخرى
09.B AC Condition	LOW COOLING.	المكيف
09.C Dash Board	MELTED PORTION CUT .	لوحة القيادة
09.D Sun Visor	LEFT SIDE MIRROR CRACKED.	حاجب الشمس
09.E Steering Wheel and control buttons	WORN OUT.	عجلة القيادة وازرار التحكم
09.F Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات
10 Battery Condition		حالة البطارية
10.A Battery Condition	WEAK,	حالة البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae