

Queue Number

2852156

Transaction Date

12 Oct 2026, 09:48:21

Site Name

840 - Emirates Auctions

Transaction Number

24480119 (CC10026) (CC10026)



Vehicle Details

Chassis Number

1N4AL3AP4D*****

Specification

Imported

Make

Nissan

Model

Altima

Model Year

2013

Color

Black

Mileage

237078 Miles

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders

REPAINTED PORTION REPAIRED , FRONT REFITTED

مدكار

01.B Paint

BODY PORTION REPAINTED PORTION REPAIRED , DENT SCRATCHES , PORTION FADED

الصبغ

01.C Doors

BOTH RIGHT SIDE REPAINTED & REAR RIGHT SIDE PORTION REPAIRED

أبواب

01.D Rusty

UNDER BODY PARTS GETTING RUSTY

صدأ

01.E Floor

UNDER FLOOR PARTS MINOR DENT SCRATCHES

الارضية

01.F Bumper

MISALIGN , PORTION SCRATCHES DENT

دعامية

01.G Bonnet

REFITTED , MISALIGN

غطاء المحرك

01.H Trunk

REPAINTED PORTION REPAIRED , MISALIGN

صندوق

02 Chassis Condition

الشاسي

02.A Chassis

CHASSIS PORTION COVER CHECK VISIBLE AREA ONLY , MUDDY OILLY

الشاسيه

03 Engine Condition

المحرك

03.A Engine Visual Condition

SHAKING , ABNORMAL SOUND , SIGN OF OIL WET GETTING RUSTY

الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition

WORN OUT

حالة المقاعد

05 Transmission Condition

الجير

05.A Gear Box Visual Condition

MINOR JERKING , SIGN OF OIL WET , GETTING RUSTY

الحالة النظرية للجير

Condition	Remarks	الحالة
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	RIGHT 2023 CRACK & LEFT SIDE 2022 CRACK WHEEL HUB COVER MISSING	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
06.C Rims Condition	DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED LEFT SIDE DAMAGE , HIGH BEAM NOT WORKING	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07.C Fog light	LENS FADED , NOT WORKING	كشاف الضباب
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY	دواسة الفرامل
08.B Disc&Drum	RUSTY	دسك وطناير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACK	ازرع
09.B Ball Joint	BOOT CRACK	مفصل كروي
09.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
10 Steering Condition		المقود
10.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
11 Interior Condition		الحالة الداخليه
11.A Other	CENTER CONSOLE BOX PANEL LOOSE , INTERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخرى
11.B Mirror	BOTH SIDE VIEW MIRROR REFLECTOR HOUSING CRACK , CENTER VIEW MIRROR LOOSE	المرآيا
11.C AC Condition	LOW COOLING , PANEL CONTROL CRACK	المكيف
11.D Power Window Switch And Glass	MAIN SWICTH BUTTON GETTING FADED	مفتاح النافذه و الزجاج
11.E Floor Matting	DIRTY	فرش الأرضيه
11.F Audio	LCD DISPLAY GETTING FADED	صوتيات
11.G Dash Board	PORTION WORN OUT , GLOVE BOX WORN OUT	لوحة القيادة
11.H Roof Ceiling	FABRIC WORN OUT , LOOSE	بطانه السقف
11.I Door Panel	PORTION WORN OUT	لوحة بطانة الباب
11.J Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.K Gear Shifting Lever	KNOB WORN OUT , SHIFTER LOCK COVER MISSING	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae