CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2945482
Transaction Date	04 Nov 2026, 14:24:23
Site Name	840 - Emirates Auctions
Transaction Number	60627727 (CC10013) (CC10013)



Vehicle Details

Chassis Number	WBAKR0107G*******
Specification	GCC Specification
Make	BMW
Model	X1
Model Year	2016
Color	Black
Mileage	97487 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Paint	BODY PORTION REPAINTED , DENTS, SCRATCHES , PORTION GETTING FADED	الصبغ
01.B Rusty	UNDER BODY PARTS , SUSPENTION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR COVERED PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN, PORTION CRACK	دعامية
01.E Vehicle Color	GRAY	لون المركبة
01.F Vehicle Model	X5	طراز المركبة
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COVERED MUDDY CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Other	FOR FULL INSPECTION MAKE STEAM WASH & REMOVE INNER FENDER UNDER FLOOR COVER FOR RECHECK	اخري
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**
04.A Gear Box Visual Condition	MINOR JERKING , PARTS GETTING RUSTY	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		**الاطارات**

Condition	Remarks	الحالة
05.A Front Tyre	2020 EXPIRED CRACKED	الاطار الامامي
05.B Rear Tyre	2020 EXPIRED CRACKED	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS GETTING FADED	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Hand Brake	SWITCH SIGN OF CRACK	فرامل اليد
07.B Disc&Drum	RUSTY	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK	ممتص الصدمات
08.B Arms	ARM BUSHES CRACK	ازرع
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY / TEA CUP HOLDER SLIDING COVER DAMAGED	اخري
09.B AC Condition	NO COOLING	المكيف
09.C Dash Board	GETTING FADED PORTION WORN OUT	لوحة القياده
09.D Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae