CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2976863
Transaction Date	12 Nov 2026, 13:06:58
Site Name	840 - Emirates Auctions
Transaction Number	23433309 (CC10010) (CC10010)



Vehicle Details

Chassis Number	WF0BB4KG8D*******
Specification	GCC Specification
Make	Ford
Model	Focus
Model Year	2013
Color	Grey
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REFITTED FRONT AND REAR REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED DENTS AND SCRATCHES PORTION RUSTY PORTION FADED	الصبغ
01.C Doors	PORTION REPAINTED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION DENT	الارضية
01.F Bumper	MISALIGN SCRATCHES	دعامية
01.G Bonnet	REFITTED REPAINTED	غطاء المحرك
01.H Sign of front accident	BUMPER FRAME FENDER FRAME BULKHEAD RADIATOR SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED OILY MUDDY,CHECKED ONLY VISIBLE AREA OK.	الشاسيه
02.B Chassis Number	VIN CHECKED ONLY STICKER	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ALL SYSTEM NOT CHECKED REFITTED OIL LEAK PARTS RUSTY.	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير

Condition	Remarks	الحالة
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024 CRACKED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024 CRACKED	الاطار الخلفي
05.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED ALL LIGHT NOT CHECKED	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK	ممتص الصدمات
08.B Arms	BUSHES CRACKED	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CUT	ربلة المقود
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR CONDITION RUSTY SIGN OF FLOODED	اخري
10.B AC Condition	NOT CHECKED	المكيف
10.C Dash Board	PORTION LOOSE	لوحة القياده
10.D Roof Ceiling	PORTION LOOSE	بطانه السقف
10.E Sun Visor	LOOSE	حاجب الشمس
10.F Odometer reading	NOT CHECKED	قراءة عداد المسافات
10.G Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
10.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.I Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.