



## TEST CERTIFICATE

|                    |                              |                  |                              |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number        | <b>840-Emirates Auctions</b> | Transaction Date | <b>20 Nov 2022, 12:04:19</b> |
| Transaction Number | <b>89642238 (CC10006)</b>    | Queue Number     | <b>626156</b>                |



|                  |                          |
|------------------|--------------------------|
| Chassis Number   | <b>WAUZZZFF1LA006494</b> |
| Engine Number    |                          |
| Vehicle Class    | <b>Car</b>               |
| Manufacturer     | <b>Audi</b>              |
| Model            | <b>A3</b>                |
| Model Year       | <b>2020</b>              |
| Color            | <b>White</b>             |
| Mileage          | <b>139611 Km</b>         |
| Fuel Type        | <b>Petrol</b>            |
| No. Of Cylinders | <b>3</b>                 |
| Specification    | <b>GCC Specification</b> |

| DEFECT                             | REMARKS  |                        |
|------------------------------------|--|------------------------|
| <b>01 Engine Condition</b>         |  | <b>المحرك</b>          |
| 01.A Visual Engine Condition       | OK   | حالة المحرك النظري     |
| <b>02 Transmission Condition</b>   |  | <b>الجير</b>           |
| 02.A Visual Gear Box Condition     | OK   | حالة الجير النظري      |
| <b>03 Tires and Rims Condition</b> |  | <b>الاطارات</b>        |
| 03.A Rear Tyre                     | BOTH SIDE 2022   | الاطار الخلفي          |
| 03.B Front Tyre                    | BOTH SIDE 2022   | الاطار الامامي         |
| <b>04 Lights</b>                   |  | <b>الاضاءة</b>         |
| 04.A Warning Light                 | WARNING LIGHT ON IN DISPLAY                            | ضوء تحذير              |
| <b>05 Body</b>                     |  | <b>جسم المركبة</b>     |
| 05.A Paint                         | PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY | الصبغ                  |
| 05.B Doors                         | FRONT LEFT SIDE PORTION REPAIRED, REPAINTED            | أبواب                  |
| 05.C Floor                         | UNDER FLOOR COVERD, CHECKED ONLY VISIBLE AREA          | الارضية                |
| <b>06 Interior Condition</b>       |  | <b>الحاله الداخليه</b> |

| DEFECT                      | REMARKS                 |               |
|-----------------------------|-------------------------|---------------|
| 06.A AC Condition           | OK                      | المكيف        |
| <b>07 Chassis Condition</b> |                         | <b>الشاسي</b> |
| 07.A Chassis                | CHECKED VISIBLE AREA OK | الشاسيه       |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.