



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **20 Jan 2023, 11:52:00**  
 Transaction Number **33167805 (CC10006)** Queue Number **660214**



Chassis Number **KNADE221476244548**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **Kia**  
 Model **Rio**  
 Model Year **2007**  
 Color **Silver**  
 Mileage **001 Km**  
 Fuel Type **Petrol**  
 No. Of Cylinders **4**  
 Specification **GCC Specification**

DEFECT	REMARKS	
<b>01 Engine Condition</b>		<b>المحرك</b>
01.A Mount	CUT .	كرسي
01.B Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING ,REFITTED OIL LEAK ,	حالة المحرك النظري
<b>02 Chassis Condition</b>		<b>الشاسي</b>
02.A Chassis Number	VIN STICKER DAMAGE .	رقم القاعدة
02.B Chassis	BOTH SIDWE CHASSIS ,REINFORCEMENT JOINT AREA BADLY RUSTY HOLE WEAK .	الشاسيه
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Floor	PORTION DENT .	الارضية
03.B Bumper	MISALIGN PORTION DAMAGE .	دعامية
03.C Paint	BODY PORTION REPAIRED ,REPAINTED .MINOR DENTS SCRATCHES ON BODY ,PORTION FADED & PORTION RUSTY	الصبغ
03.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY .	صدأ
<b>04 Steering Condition</b>		<b>المقود</b>
04.A Steering Boot	CUT ,	ريلة المقود
04.B Steering Box	OIL LEAK .	جهاز المقود

DEFECT	REMARKS	
<b>05 Tires and Rims Condition</b>		<b>الاطارات</b>
05.A Front Tyre	BOTH SIDE 2019 CRACKED .	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2019 CRACKED .	الاطار الخلفي
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Shock Absorber	LEAK ,	ممتص الصدمات
06.B Arms	LOWER ARM BUSHES CRACKED .	ازرع
<b>07 Interior Condition</b>		<b>الحالة الداخليه</b>
07.A Odometer reading	NOT CHECKED .	قراءة عداد المسافات
07.B Sun Visor	LOOSE .	حاجب الشمس
07.C Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
07.D AC Condition	NOT CHECKED .	المكيف
<b>08 Transmission Condition</b>		<b>الجير</b>
08.A Visual Gear Box Condition	REFITTED OIL LEAK & NOT CHECKED .	حالة الجير النظري
08.B Road Test	NOT CHECKED .	فحص علي الطريق
<b>09 Lights</b>		<b>الاضاءة</b>
09.A Tail Light	RIGHT SIDE CRACKED .	الانارة
09.B Fog light	FADED .	كشاف الضباب
09.C Head Light	LENS FADED ,ALL LIGHTS NOT CHECKED .	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.