



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	09 Oct 2021, 18:03:47
Transaction Number	69591094 (CC10006)	Queue Number	312309



Chassis Number	WDD2193761A027880
Engine Number	
Vehicle Class	Car
Manufacturer	Mercedes
Model	CLS 55 AMG
Model Year	2005
Color	White
Mileage	0 N/A

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	PORTION REPAIRED & REPAINTED	مدكار
01.B Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR COVERD	الارضية
01.E Bumper	REPAINTED	دعامية
01.F Roof	SLYDING ROOF INNER SHEILD HANDLE MISSING	السقف
01.G Bonnet	SHOCK WEAK	غطاء المحرك
01.H Pillars	BOTH SIDE INNER COVER DAMAGED & LOSE	القوائم
02 Chassis Condition		الشاصي
02.A Chassis	VISABLE AREA OK	الشاسيه
03 Engine Condition		المحرك
03.A Other	OIL LEAK	اخرى
04 Seats Condition		المقاعد
04.A Other	OK	اخرى
05 Exhaust System		نظام العادم
05.A Modification	MODIFIED	تعديلات
05.B Other	WELDED & REPAIRED	اخرى

DEFECT	REMARKS	
06 Transmission Condition		الجير
06.A Gear Box	OIL LEAK	الجير
06.B Propeller Shaft	POPELLAR SHAFT RUBBER CRACKED	ناقل الحركة
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH 2019	الاطار الامامي
07.B Rear Tyre	BOTH 2019	الاطار الخلفي
08 Wipers and Arms		المساحات
08.A Other	OK	اخرى
09 Lights		الاضاءة
09.A Head Light	COVER CRACKED	الاضاءة الرئيسية
09.B Tail Light	RIGHT SID FOG LAMP NOT WORKING & REAR COVER CRACKED	الادارة
09.C Warning Light	SRS ON	ضوء تحذير
10 Brake Condition		الفرامل
10.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
10.B Hand Brake	HANDLE DAMAGED	فرامل اليد
11 Suspension System		ممتص الصدمات
11.A Arms	FRONT BOTH LOWER ARM BUSHES MINOR CRACKED	ازرع
11.B Shock Absorber	BUSHES CUT	ممتص الصدمات
12 Steering Condition		المقود
12.A Steering Boot	LEAK	ربلة المقود
12.B Axel	BOOT CUT & LEAKING	اكسلات
13 Interior Condition		الاجزاء الداخلية
13.A Other	DASHBOARD AND CONSOLE BOX DAMAGED	اخرى
13.B Mirror	LEFT SIDE AUTO NOT WORK PROPERLY	المرايا

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.