CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2869168
Transaction Date	14 Oct 2026, 16:55:01
Site Name	840 - Emirates Auctions
Transaction Number	74030677 (CC10009) (CC10012)



Vehicle Details

Chassis Number	LFPH4ACP9R*******
Specification	GCC Specification
Make	HONGQI
Model	H5
Model Year	2024
Color	Black
Mileage	9605 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	RIGHT SIODE BOTH REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	RIGHT SIODE BOTH REPAINTED PORTION REPAIRED , REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR FRONT CHASSIS COVERED CHECKED VISIBLE AREA ONLY	الارضية
01.F Roof	PORTION DENT	السقف
01.G Pillars	RIGHT SIDE PILLAR ROCKER PANEL REPAIRED	القوائم
01.H Trunk	MISALIGN	صندوق
01.I Sign of front accident	FRONT BUMPER FRAME BULK HEAD , RIGHT SDE CROSS MEMEBR REPAIRED	وجود مؤشر لحادث في المقدمة
01.J Sign of side accident		وجود مؤشر لحادث في الجانب
02 Chassis Condition		**الشاصي**
02.A Chassis	FORNT CHASSIS COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	REMOVE FRONT CHASSIS FENDER UNDER COVERS FOR RECHECK PROPERLY	اخري
02.C Chassis Number	CHASSIS NUMBER STICKER PORTION LOOSE	رقم القاعدة
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	MINOR SHAKING PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	PARTS GETTING RUSTY	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	LEFT SIDE 2023 , RIGHT SIDE 2025	الاطار الامامي
05.B Rear Tyre	LEFT SIDE 2025 , RIGHT SIDE 2023	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CRACKED	ازرع
08 Interior Condition		الحاله الداخليه
08.A Other	INTERIOR PARTS GETTING RUSTY	اخري
08.B AC Condition	OK	المكيف

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae