

Queue Number 2585430

Transaction Date 28 Jul 2026, 15:52:50

Site Name
840 - Emirates AuctionsTransaction Number
33352228 (CC10006) (CC10019)

Vehicle Details

Chassis Number	MMDAF26J7L*****
Specification	GCC Specification
Make	Mitsubishi
Model	Attrage
Model Year	2020
Color	Grey
Mileage	114219 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	3

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE & REAR RIGHT SIDE REPAINTED, PORTION REPAIRED,FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENTS & SCRATCHES,	الصبغ
01.C Doors	FRONT RIGHT SIDE REPAINTED, PORTION REPAIRED,	أبواب
01.D Rusty	UNDER BODY PARTS, SUSPENTION GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION DENT, PORTION RUSTY	الارضية
01.F Bumper	MISALIGN,PORTION DAMAGED	دعامية
01.G Bonnet	REPAINTED, PORTION REPAIRED REFITTED & PORTION DAMAGED	غطاء المحرك
01.H Other	FRONT BUMPER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED	اخرى
01.I Trunk	REPAINTED, PORTION REPAIRED,	صندوق
01.J Sign of front accident		وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	OK	الشاسيه
--------------	----	---------

03 Engine Condition

المحرك

03.A Mount	BUSHES CRACKED	كرسي
03.B Engine Visual Condition	SHAKING,REFITTED,OIL LEAK,PARTS RUSTY	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	EXTRA COVER	حالة المقاعد
---------------------	-------------	--------------

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	JERKING,REFITTED,OIL WET,PARTS RUSTY	الحالة النظرية للجير
05.B Gear Box Mount	BUSH CRACKED	كرسي الجير
05.C Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2021 CRACKED EXPIRED	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LEFT SIDE BRACKET DAMAGED	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK	ممتص الصدمات
08.B Arms	BUSHES CUT	ازرع
08.C Ball Joint	BOOT CUT	مفصل كروي
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
10 Interior Condition		الحالة الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY,	اخرى
10.B AC Condition	OK	المكيف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae