CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899784
Transaction Date	23 Oct 2026, 14:39:30
Site Name	840 - Emirates Auctions
Transaction Number	78739423 (CC10010) (CC10010)



Vehicle Details

Chassis Number	JNKBV61E67*******
Specification	GCC Specification
Make	Infiniti
Model	G35
Model Year	2007
Color	Blue
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	REPAIRED REPAINTED REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Doors	PORTION REPAINTED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.F Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.G Bonnet	REPAIRED REPAINTED REFITTED.	غطاء المحرك
01.H Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT CHASSIS END DENT CHASSIS COMPLETE COVERED CHECKED ONLY VISIBLE AREA.	الشاسيه
02.B Other	REMOVE FENDER UNDER COVER FOR INSPECTION .	اخري
03 Engine Condition		**المحرك**
03.A Mount	BUSHES CRACKED.	كرسي
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2018 EXPIRED CRACKED.	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2018 EXPIRED CRACKED .	الاطار الخلفي
05.C Rims Condition	DENTS SCRATCHES ,	حالة الجنوط
06 Wipers and Arms		المساحات
06.A Other	TANK CAP MIASSING	اخري
07 Lights		الاضاءة
07.A Head Light	LENS FADED. ALL LIGHT NOT CHECKED.	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CRACKED .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK. .	جهاز المقود
10.C Axle	BOOT CRACKED	اكسلات
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
11.B Mirror	LOOSE.	المرايا
11.C FLoor Matting	CENTER CONSOLE BOX COVER CRACKED.	فرش الأرضيه
11.D Dash Board	CRACKED.	لوحة القياده
11.E Roof Ceiling	PORTION LOOSE	بطانه السقف
11.F Odometer reading	NOT CHECKED.	قراءة عداد المسافات
11.G Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
11.H Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
11.I Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the

vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**