

Queue Number	2866290	Transaction Date	14 Oct 2026, 12:56:28
Site Name	840 - Emirates Auctions	Transaction Number	17618180 (CC10013) (CC10011)



Vehicle Details

Chassis Number	JN8AY2NY5G*****
Specification	GCC Specification
Make	Nissan
Model	Patrol
Model Year	2016
Color	White
Mileage	120280 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Fenders	FRONT BOTH SIDE REPAINTED PORTION REPAIRED,RIGHT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION FADED GETTING RUSTY,PORTION TOUCHUP	الصبغ
01.C Doors	FRONT BOTH SIDE REPAINTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR MOUNT RUBBER DRY CRACK	الارضية
01.F Bumper	MISALIGN,PORTION CRACKED	دعامية
01.G Roof	REPAINTED PORTION REPAIRED	السقف
01.H Bonnet	REPAINTED PORTION REPAIRED,REFITTED	غطاء المحرك
01.I Trunk	AUTO NOT WORKING PROPERLY,REAR SWITCH DAMAGED	صندوق

02 Chassis Condition الشاسي

02.A Chassis	CHASSIS FRAME GETTING RUSTY DIRTY	الشاسيه
--------------	-----------------------------------	---------

03 Engine Condition المحرك

03.A Engine Visual Condition	OPEN REFITTED , OIL LEAK , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition المقاعد

04.A Seat Condition	FRONT BOTH SIDE SEAT LOOSE,LEFT PORTION DAMAGED,RIGHT ADJUSTMENT NOT WORKING PROPERLY SWITCH REPOSITION	حالة المقاعد
---------------------	---	--------------

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED , HOUSING BOLT MISSING , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACK GETTING WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Indicator & Hazard light	LEFT SIDE MIRROR INDICATOR LIGHT COVER PORTION CRACK	الاشارات
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK	ممتص الصدمات
08.B Arms	ARM BUSHES DRY CRACK	ازرع
08.C Ball Joint	BOOT CUT	مفصل كروي
08.D Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Steering Condition		المقود
09.A Steering Oil	OIL LEAK	زيت المقود
10 Interior Condition		الحالة الداخليه
10.A Other	COOL BOX COVER PORTION CUT,CENTER CONSOLE BOX PANEL PORTION LOOSE / INTERIOR PARTS GETTING RUSTY	اخرى
10.B AC Condition	OK	المكيف
10.C Power Window Switch And Glass	SWITCH PORTION WORN OUT	مفتاح النافذه و الزجاج
10.D FFloor Matting	EXTRA FITTING	فرش الأرضيه
10.E Audio	REAR LEFT SIDE LCD CASE PORTION DAMAGED	صوتيات
10.F Dash Board	MELTED PORTION CRACK WORN OUT	لوحة القيادة
10.G Roof Ceiling	DIRTY	بطانه السقف
10.H Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.I Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.J Gear Shifting Lever	KNOB WORN OUT,SHIFT LOCK COVER MISSING	ذراع نقل السرعات
10.K Engine Start Button	BUTTON,REMOTE WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the

vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae