

Queue Number 2827636

Transaction Date 10 Oct 2026, 09:49:08

Site Name
840 - Emirates AuctionsTransaction Number
54971194 (CC10021) (CC10021)

Vehicle Details

Chassis Number	MALC281CXJ*****
Specification	GCC Specification
Make	Hyundai
Model	Creta
Model Year	2018
Color	Grey
Mileage	161432 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT RIGHT SIDE PORTIN REPAINTED,PORITION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORITION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.C Doors	FRONT RIGHT SIDE PORTION REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED,CHECKED VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	NOT CHECKED	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

05 Tires and Rims Condition

الاطارات

05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط

Condition	Remarks	الحالة
06 Brake Condition		الفرامل
06.A Disc&Drum	RUSTY	دسك و طناوير الفرامل
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CRACK	ازرع
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR PARTS GETTING RUSTY	اخري
08.B AC Condition	NOT CHECKED	المكيف
08.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.D Gear Shifting Lever	WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae