



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>10 May 2022, 16:50:37</b>
Transaction Number	<b>69750024 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>WBAEJ110X2AF79728</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>BMW</b>
Model	<b>Z8</b>
Model Year	<b>2002</b>
Color	<b>Silver</b>
Mileage	<b>220397 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Lights</b>		<b>الاضاءة</b>
01.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
01.B Fog light	NOT WORKING	كشاف الضباب
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Bumper	,MIASLIGN	دعامية
02.B Paint	BODY TOTALLY REPAINTED , PORTION REPAIRED DENTS SCRATCHES ON BODY	الصبغ
02.C Bonnet	SHOCK WEAK	غطاء المحرك
02.D Sign of front accident		وجود مؤشر لحادث في المقدمة
<b>03 Tires and Rims Condition</b>		<b>الاطارات</b>
03.A Rear Tyre	BOTH SIDE 2016 & EXPIRED	الاطار الخلفي
03.B Front Tyre	BOTH SIDE 2016 & EXPIRED	الاطار الامامي
<b>04 Engine Condition</b>		<b>المحرك</b>
04.A Visual Engine Condition	MINOR OIL LEAK REFITTED	حالة المحرك النظري
04.B Mount	MOUNT RUBBER CRACKED	كرسي
<b>05 Transmission Condition</b>		<b>الجير</b>

DEFECT	REMARKS	
05.A Visual Gear Box Condition	MINOR OIL LEAK REFITTED	حالة الجير النظري
05.B Road Test	NOT CHECK	فحص علي الطريق
<b>06 Interior Condition</b>		<b>الحاله الداخليه</b>
06.A AC Condition	OK	المكيف
06.B Dash Board	LEFT SIDE AROUND LIGHT OFF ON COVER LOOSE	لوحة القيادة
<b>07 Chassis Condition</b>		<b>الشاسي</b>
07.A Chassis	FRONT LEFT SIDE CHASSIS REPLACED	الشاسيه
07.B Chassis Number	STICKER GETTING WORN OUT	رقم القاعدة
<b>08 Steering Condition</b>		<b>المقود</b>
08.A Steering Oil	MINOR OIL LEAK	زيت المقود
08.B Steering Boot	BOOT CUT	ربلة المقود

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



X FAILED

Plate Details :	D 99744 Dubai Private		
Chassis No :	WBAEJ110X2AF79728		
Vehicle Make :	BMW		
Vehicle Model :	Z8		
Vehicle Class :	Light Vehicle		
Body Type :	Coupe		
Fuel :	Benzene		
Color :	Silver		
Drive Direction :	--		
Dimensions : (H x W x L)	-- x -- x --		
Current Odometer :	220401 Kms.		
Origin :	Germany	Model Year :	2002
Gear Type :	Manual	Engine Size :	5000 CC
Engine No :	61052664	Horse Power :	406
Axles No :	2	Cylinders :	8
No Of Doors :	2	No Of Seats :	2
G. V. W. :	1900 Kgs.	Empty Weight :	1699 Kgs.

⚠ Retest can be done only in Dubai

Certificate Number :	5-TAS-2022-16754746		
Inspection Date :	12-05-2022		
Certificate Print Date :	12-05-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	13 min 10 sec		
Appointment Ref Number :	--		
Start Time :	10:04	End Time :	10:17
Lane :	02	Token No. :	110
Attempt :	1	Prints No. :	1

## Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
3 %	1 %	2 %	0 %
Vehicle on Petrol HC Reading	0 PPM VOL		

## Inspection Findings

Defects	Issue	Severity
Tire change all old 2016	Date of manufactured tampered or expired	Major

Inspection Remarks: FRONT LEFT SIDE CHASSIS , FLOOR , WHEEL ARC , FENDER FRAME REPAIRED.OLD PASS

## Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
71051	Cash	16754746	AED 170 Collected on 12/05/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Sittu Paloth Sreesan Paloth

ⓘ This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

ⓘ Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.