

Queue Number 2836724

Transaction Date 05 Oct 2026, 13:20:17

Site Name
840 - Emirates AuctionsTransaction Number
38742617 (CC10009) (CC10012)

Vehicle Details

Chassis Number	SALWA2BE2N*****
Specification	Imported
Make	Range Rover
Model	SVR
Model Year	2022
Color	Blue
Mileage	162890 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Fenders	REAR BOTH SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	FRONT RIGHT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS FULLY COVERED MUDDY OILY CHECKED VISIBLE AREA ONLY, REQUIRE STEAM WASH FOR RECHECK PROPERLY	الارضية
01.F Bonnet	MODIFIED	غطاء المحرك
01.G Trunk	FIBER PAINT NOT CHECK	صندوق
01.H Vehicle Color	BLUE BLACK	لون المركبة
01.I Vehicle Model	AS PER PREVIOUS HIS ,SPORT SVR	طراز المركبة

02 Chassis Condition الشاسي

02.A Chassis	CHASSIS FULLY MUDDY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Chassis Number	LAMINATED, CHECKED ON STICKER ONLY	رقم القاعدة

03 Engine Condition المحرك

03.A Engine Visual Condition	OIL LEAK REFITTED GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---------------------------------	-----------------------

04 Seats Condition المقاعد

04.A Seat Condition	DRIVER SEAT SIDE COVER PORTION CRACK	حالة المقاعد
---------------------	--------------------------------------	--------------

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	OIL WET REFITTED,MINOR JERKING	الحالة النظرية للجير
05.B DIFFERENTIAL	REAR OIL LEAK	الدفرنشل
05.C Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2026	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2026	الاطار الخلفي
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Other	SUSPENSION REFITTED	اخرى
09 Interior Condition		الحالة الداخليه
09.A AC Condition	OK	المكيف
09.B Dash Board	LEATHER REPLACED , PORTION LOOSE	لوحة القيادة

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae