CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2965709
Transaction Date	09 Nov 2026, 13:03:51
Site Name	840 - Emirates Auctions
Transaction Number	90147463 (CC10010) (CC10010)



Vehicle Details

Chassis Number	KMHDG41C6D*******
Specification	GCC Specification
Make	Hyundai
Model	Elantra
Model Year	2013
Color	Red
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	DENT MISALIGN ,REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Doors	REPAINTED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.F Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
01.G Bonnet	REPAINTED	غطاء المحرك
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
04.B Road Test	NOT CHECKED.	فحص علي الطريق
05 Tires and Rims Condition		الاطارات

Condition	Remarks	الحالة
05.A Front Tyre	BOTH SIDE 2021 EXPIRED CRACKED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2021 EXPIRED CRACKED	الاطار الخلفي
05.C Spare Tire &Tools	MISSING	الاطار الاحتياطي و العدة
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CRACKED.	ازرع
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED.	اخري
09.B Mirror	RIGHT SIDE DAMAGED .	المرايا
09.C AC Condition	NOT CHECKED.	المكيف
09.D Dash Board	PORTION DAMAGED ,PARTS MISSING	لوحة القياده
09.E Sun Visor	LOOSE	حاجب الشمس
09.F Odometer reading	NOT CHECKED.,	قراءة عداد المسافات
09.G Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
09.H Steering Wheel and control buttons	WORN OUT PARTS MISSING	عجلة القيادة وازرار التحكم
09.I Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae