CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2978266
Transaction Date	13 Nov 2026, 15:07:35
Site Name	840 - Emirates Auctions
Transaction Number	23404463 (CC10013) (CC10011)



Vehicle Details

Chassis Number	WBAKU6100F*******
Specification	GCC Specification
Make	BMW
Model	X6
Model Year	2015
Color	Black
Mileage	115247 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE FIBER PAINT NOT CHECK	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.C Doors	REAR LEFT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COVERED DIRTY	الارضية
01.F Bumper	MISALIGN SCRATCHES	دعامية
01.G Pillars	LEFT SIDE C/PILLAR OUTER PANEL REPAIRED	القوائم
01.H Trunk	REAR SWITCH MELTED	صندوق
01.I Vehicle Color	BROWN	لون المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED MUDDY DIRTY CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Other	FOR FULL INSPECTION MAKE STEAM WASH & REMOVE INNER FENDER UNDER ENGINE FLOOR COVER FOR RECHECK	اخري
03 Engine Condition		المحرك
03.A Smoke	MINOR WHITE	دخان
03.B Engine Visual Condition	REFITTED , PARTS GETTING RUSTY , OIL WET	الحالة النظريه للمحرك
04 Seats Condition		المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	FRONT BOTH SEAT,SIDE BACK COVER LOOSE	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR JERKING , REFITTED , HOUSING BOLT MISSING , OIL LEAK	الحالة النظريه للجير
05.B Propeller Shaft	FLANGE RUBBER CRACK	ناقل الحركة
05.C Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Wipers and Arms		المساحات
07.A Other	BOTTLE PART DAMAGED / CAP MISSING	اخري
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK	ممتص الصدمات
08.B Arms	ARM BUSHES CRACK	ازرع
08.C Ball Joint	BOOT CUT	مفصل كروي
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الرودات
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CUP HOLDER SLIDING COVER DAMAGED / INTERIOR PARTS MINOR GETTING RUSTY	اخري
10.B AC Condition	OK	المكيف
10.C Power Window Switch And Glass	REAR BOTH SIDE CURTAIN HANDLE DAMAGED,QUARTER GLASS BEADING DAMAGED	مفتاح النافذه و الزجاج
10.D Dash Board	LEATHER LOOSE / PORTION WORN OUT CRACK	لوحة القياده
10.E Roof Ceiling	PORTION WORN OUT LOOSE	بطانه السقف
10.F Sun Visor	LEFT SIDE MIRROR CASE PORTION CRACK	حاجب الشمس
10.G Door Panel	PORTION LOOSE WORN OUT	لوحة بطانة الباب
10.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.I Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
10.J Engine Start Button	WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the

vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**