CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899757
Transaction Date	24 Oct 2026, 11:35:36
Site Name	840 - Emirates Auctions
Transaction Number	66855126 (CC10021) (CC10021)



Vehicle Details

Chassis Number	KL1PJ5C58H*******
Specification	GCC Specification
Make	Chevrolet
Model	Cruze
Model Year	2017
Color	Black
Mileage	255076 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED	الصبغ
01.B Floor	UNDER FLOOR THICK RUST PROOFED PORTION DENTS, MUDDY	الارضية
01.C Bumper	MISALIGN , PORTION DAMAGE	دعامية
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERD MUDDY , CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		المحرك
03.A Mount	LOWER MOUNT BUSHES CRACK	كرسي
03.B Engine Visual Condition	ENGINE NOT STARTING , ALL SYSTEM NOT CHECKED DUE OF ELECTRICAL FAULT , MINOR OIL LEAK	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION WORN OUT	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED DUE OF ELECTRICAL FAULT , REFITTED PARTS GETTING RUSTY , SIGN OF OIL WET	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACK	الاطار الامامي

Condition	Remarks	الحالة
06.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACK	ازرع
09.B Stabilizer Bar And Link Rod	PORTION WORN OUT	عمود التوازن و مثبت عمود التوازن
10 Steering Condition		المقود
10.A Tie Rod End	PORTION WORN OUT	مؤخرة الرودات
11 Interior Condition		الحاله الداخليه
11.A Other	CENTER CONSOLE BOX COVER WORN OUT , INETRIOR PARTS GETTING RUSTY	اخري
11.B Mirror	CENTER VIEW MIRROR FADED	المرايا
11.C AC Condition	NOT CHECK	المكيف
11.D Dash Board	PORTION WORN OUT	لوحة القياده
11.E Roof Ceiling	PORTION WORN OUT	بطانه السقف
11.F Sun Visor	PORTION WORN OUT	حاجب الشمس
11.G Door Panel	PORTION WORN OUT	لوحة بطانة الباب
11.H Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
11.I Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات
12 Engine Cooling System		نظام تبريد المحرك
12.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.