



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>19 Jan 2022, 16:08:43</b>
Transaction Number	<b>99490406 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>JN1CC13CX8T013223</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Nissan</b>
Model	<b>Tiida</b>
Model Year	<b>2008</b>
Color	<b>Grey</b>
Mileage	<b>185650 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Bonnet	PORTION REPAIRED & REPAINTED	غطاء المحرك
01.B Bumper	REPAINTED & MISALIGN	دعامية
01.C Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY, PORTION FADED	الصبغ
01.D Other	FRONT FENDER FRAME ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT REPAIRED	اخرى
01.E Fenders	FRONT LEFT SIDE PORTION REPAIRED, REPAINTED & RIGHT SIDE PORTION REPAINTED	مدكار
<b>02 Interior Condition</b>		<b>الحاله الداخليه</b>
02.A AC Condition	NOT COOLING	المكيف
02.B Mirror	BOTH SIDE AUTO NOT WORKING	المرايا
02.C Sun Visor	LEFT SIDE MISSING	حاجب الشمس
<b>03 Lights</b>		<b>الاضاءة</b>
03.A Head Light	LENS FADED	الاضاءة الرئيسية
03.B Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
03.C Brake Light	LEFT SIDE COVER CRACKED	نور الفرامل

DEFECT	REMARKS	
<b>04 Chassis Condition</b>		<b>الشاصي</b>
04.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED	الشاسيه
<b>05 Seats Condition</b>		<b>المقاعد</b>
05.A Seat Condition	DRIVER SEAT DAMAGED	حالة المقاعد
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Arms	FRONT LOWER ARM BUSHES CRACKED	ازرع
06.B Suspension Subframe	SUSPENTION SUB FRAME GETTING RUSTY	
<b>07 Tires and Rims Condition</b>		<b>الاطارات</b>
07.A Rear Tyre	BOTH SIDE 2014/2017 EXPIRED & CRACKED	الاطار الخلفي
07.B Front Tyre	BOTH SIDE 2020	الاطار الامامي
<b>08 Steering Condition</b>		<b>المقود</b>
08.A Axel	AXL CASE LEAKING	اكسلات
<b>09 Transmission Condition</b>		<b>الجير</b>
09.A Road Test	NOT CHECK	فحص علي الطريق
09.B Visual Gear Box Condition	OK	حالة الجير النظري
<b>10 Engine Condition</b>		<b>المحرك</b>
10.A Visual Engine Condition	OIL LEAK & REFITTED	حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.