



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	08 May 2022, 17:24:20
Transaction Number	37670906 (CC10006)	Queue Number	312309



Chassis Number	SALSK25469A189747
Engine Number	
Vehicle Class	Car
Manufacturer	Land Rover
Model	Range Rover Sport HSE
Model Year	2009
Color	Black
Mileage	37332 Miles
Fuel Type	Petrol
No. Of Cylinders	8
Specification	USA Imported

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED,MINOR DENT,SCRATCHES	الصبغ
01.B Bonnet	PORTION REPAINTED	غطاء المحرك
01.C Rusty	UNDER BODY PARTS & SUSPENTION, FLOOR, CHASSIS RUSTY	صدأ
01.D Trunk	NOT OPENING FOR CHECK	صندوق
01.E Roof	REPAINTED	السقف
02 Interior Condition		الحالة الداخليه
02.A Roof Ceiling	LOOSE	بطانه السقف
02.B Other	CENTER CONSOLE BOX LOCK DAMAGED & CUP SLIDING COVER NOT CLOSING	اخرى
02.C AC Condition	NOT CHECK	المكيف
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH SIDE 2013 EXPIRED,CRACKED	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2017/2006 CRACKED,EXPIRED	الاطار الخلفي
04 Transmission Condition		الجير
04.A Road Test	NOT CHECK	فحص علي الطريق

DEFECT	REMARKS	
04.B Visual Gear Box Condition	NOT CHECK	حالة الجير النظري
05 Wipers and Arms		المساحات
05.A Wiper Arm &Blade	NOT CHECK	ازرع المساحات والشفرات
06 Engine Condition		المحرك
06.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK & OIL LEAK & STARTER 1 BOLT MISSING , 1 BOLT LOOSE	حالة المحرك النظري
07 Chassis Condition		الشاسي
07.A Chassis	COMPLETELY RUSTY	الشاسيه
08 Lights		الاضاءة
08.A Head Light	ALL LIGHTS NOT CHECK	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.