

Queue Number 2822500

Transaction Date 01 Oct 2026, 16:27:27

Site Name
840 - Emirates AuctionsTransaction Number
39586566 (CC10009) (CC10012)

Vehicle Details

Chassis Number	SALYK2FVXL*****
Specification	Imported
Make	Range Rover
Model	Velar
Model Year	2020
Color	White
Mileage	76207 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	RIGHT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	RIGHT SIDE REFITTED	أبواب
01.D Rusty	UNDER BODY APRTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS NOT VISIBLE	الارضية
01.F Trunk	MISALIGN	صندوق
01.G Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETELY COVERED, CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	FOR RECHECK PROPERLY REMOVE ALL UNDER COVERS	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK REFITTED, GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	----------------------------------	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	DRIVER SEAT SIDE DAMAGED	حالة المقاعد
---------------------	--------------------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	OIL WET REFITTED JERKING, GETTING RUSTY	الحالة النظرية للجير
--------------------------------	---	----------------------

Condition	Remarks	الحالة
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Interior Condition		الحالة الداخليه
08.A Other	CENTER CONSOLE BOX SCRATCHES, INNER PARTS GETTING MINOR RUSTY	اخرى
08.B AC Condition	OK	المكيف
08.C Power Window Switch And Glass	FRONT LEFT SIDE SWITCH PANEL LOOSE	مفتاح النافذه و الزجاج

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae