



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	05 May 2022, 18:01:53
Transaction Number	82547141 (CC10008)	Queue Number	312309



Chassis Number	1YVHZ8CH7B5M06365
Engine Number	
Vehicle Class	Car
Manufacturer	Mazda
Model	6
Model Year	2011
Color	Silver
Mileage	50447 Miles
Fuel Type	Petrol
No. Of Cylinders	4
Specification	USA Imported

DEFECT	REMARKS	
01 Lights		الاضاءة
01.A Fog light	LEFT SIDE NOT WORKIING	كشاف الضباب
01.B Head Light	RIGHT SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
02 Body		جسم المركبة
02.A Fenders	FRONT LEFT SIDE PORTION REPAIRED,REPAINTED	مذكار
02.B Bonnet	PORTION REPAIRED, REPAINTED & REFITTED,MISALIGN	غطاء المحرك
02.C Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
02.D Doors	LEFT SIDE BOTH PORTION REPAIRED,REPAINTED	أبواب
02.E Floor	MINOR DENT	الارضية
02.F Rusty	UNDER BODY PARTS, SUSPENSION , CHASSIS ,FLOOR GETTING RUSTY	صدأ
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2018/2017 CRACKED & EXPIRED	الاطار الخلفي
04 Chassis Condition		النشاصي
04.A Chassis	OK	النشاصيه

DEFECT	REMARKS	
05 Transmission Condition		الجير
05.A Visual Gear Box Condition	SIGN OF OIL WET	حالة الجير النظري
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Brake Condition		الفرامل
06.A Brake Oil	BRAKE FLUID CAP MISSING	زيت الفرامل
07 Battery Condition		حالة البطارية
07.A Battery bracket	MISSING	حامل البطارية
08 Engine Condition		المحرك
08.A Visual Engine Condition	OK	حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.