CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2923741
Transaction Date	30 Oct 2026, 16:56:17
Site Name	840 - Emirates Auctions
Transaction Number	69588873 (CC10013) (CC10019)



Vehicle Details

Chassis Number	SALVA2BG0H*******
Specification	GCC Specification
Make	Range Rover
Model	Evoque
Model Year	2017
Color	Brick
Mileage	122612 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE FIBER PAINT NOT CHECKED	مدكار
01.B Paint	BODY PORTION,REPAINTED ,PORTION REPAIRED ,MINOR DENTS SCRATCHES	الصبغ
01.C Doors	REAR RIGHT SIDE REPAINTED ,PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION COVERED RUST PROOFED	الارضية
01.F Bumper	MISALIGN,PORTION DAMAGED	دعامية
01.G Bonnet	REPAINTED ,PORTION REPAIRED,REFITTED	غطاء المحرك
01.H Trunk	FIBER PAINT NOT CHECKED	صندوق
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COVERED DIRTY CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Chassis Number	VIN LAMINATED	رقم القاعدة
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	COMPONENTS REFITTED , ABNORMAL NOISY , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Exhaust System		**نظام العادم**
04.A Other	LEAK NOISY	اخري
05 Transmission Condition		**الجير**

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	DIRTY , PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR SCRATCHES	حالة الجنوط
07 Brake Condition		الفرامل
07.A Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	ARM BUSHES DRY CRACK	ازرع
08.B Ball Joint	BOOT WORN OUT	مفصل كروي
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR MODIFIED & CENTER CONSOLE BOX LOCK DAMAGED	اخري
09.B Dash Board	LEATHER REPAIRED	لوحة القياده
09.C Roof Ceiling	PORTION LOOSE	بطانه السقف
09.D Sun Visor	LEFT SIDE PORTION LOOSE	حاجب الشمس
09.E Door Panel	PORTION LOOSE	لوحة بطانة الباب
10 Engine Cooling System		نظام تبريد المحرك
10.A Coolant tank	SIGN OF PIPE LEAK	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae