



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20964497	Plate Category	: PRIVATE
Transaction Date	: 06 SEP 2020 14:25:49	Plate Number	: 077 EA
Queue Number	: 216574	Import Doc. Ref.	:
Chassis Number	: KMHCT41D0EU616077	Manufacturer/Model	: HYUNDAI/ACCENT
Engine Number	:	Model Year	: 2014
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: GREY
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
03 Brake System		تنظيم الفرامل
03.01 - Brake Efficiency Front Wheels Left And Right Hands		قوة فرامل المحور الامامي
		BRAKE ROTORS RUSTY/ BRAKE PADS WORN OUT
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
		TIRES EXPIRED/ SIDEWALL CRACKS ROADTEST NOT DONE
04.07 - Rims		الرنجات
		SCRATCHES
05 Body		الهيكل
05.02 - Paint		الصيغ
		BODY SCRATCHES/ DENTS/ PAINT PORTIONS FADED
05.07 - Floor		الارضية
		UNDERFLOOR DENTS
05.08 - Chassis (Frame)		الشاصية
		REAR LEFT SIDE MEMBER END REPAIRED/ INNER SKIRT DENT/ FRONT RIGHT SIDE MEMBER UNDERSKIRT SLIGHT DENT
06 General Items		الاشياء العامة
06.02 - Wiper Arms		أذرع ماسحات الزجاج
		WIPER STALK BROKEN
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها
		INTERIOR PARTLY WORN OUT/ HOOD LATCH BROKEN
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
		145810 KMS
09 Auction		الفحص الكامل
09.15 - Sign Of Rear Accident		أثر حادث في مؤخرة المركبة
		BACK PANEL REPAIRED
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
		REAR RIGHT FENDER DENT
09.25 - Body Repainted		أثر صيغ في المركبة
		BODY PORTIONS REPAINTED

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

Test Certificate



Vehicle
Registration



X FAILED

Possession Certificate : 64286311

Chassis No : KMHCT41D0EU616077

Vehicle Make : HYUNDAI

Vehicle Model : ACCENT

Vehicle Class : Light Vehicle

Body Type : SALOON

Fuel : Benzene

Color : Silver

Drive Direction : --

Dimensions : (H x W x L) -- x -- x --

Current Odometer : 145811 Kms.

Origin : South Korea Model Year : 2014

Gear Type : -- Engine Size : 2000 CC

Engine No : G4FCDU53... Horse Power : --

Axles No : 2 Cylinders : 4

No Of Doors : 4 No Of Seats : 5

G. V. W. : 1800 Kgs. Empty Weight : 1400 Kgs.

Certificate Number : 5-TAS-2020-12512513

Inspection Date : 09-09-2020

Certificate Print Date : 09-09-2020

Services : Registration Test

Vehicle Testing Partner : Tasjeel

Vehicle Testing Center : Tasjeel Emirates Auction

Total Time Taken :
13 min 37 sec

Appointment Ref Number : --

Start Time : 11:45

End Time : 11:59

Lane : 01

Token No. : 4

Attempt : 1

Prints No : 1

Parameter Readings

Service brake imbalance on
front axle
2 %

Service brake imbalance on
rear axle
25 %

Parking brake imbalance
between LHS and RHS
44 %

Vehicle on Petrol CO
Reading
0.33 %

Vehicle on Petrol HC
Reading
144 PPM VOL

Inspection Findings

Defects	Issue	Severity
Dip beams(Low Beams) headlight left side low beam not working & right side fog light	Busted bulb	Major
Reflector Triangle	Not Available	Major
Paint repair body portion paint faded	Totally faded	Major
Tire change all tires cracks & old 2013	Cracked	Major

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	2000	1600	
Paint Different color	Silver	Gray	Verified

Inspection Remarks:

REAR LEFT SIDE MEMBER END REPAIRED/ INNER SKIRT DENT/ FRONT RIGHT SIDE MEMBER UNDERSKIRT SLIGHT DENT

Payment Details

Inspection Performed by 59460	Payment Method VTP Credit Account	Transaction Number 12512513	Service Fees AED 170 Collected on 09/09/2020
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Raul Canceran Galang

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

1 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسئولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995

