CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2923734
Transaction Date	30 Oct 2026, 16:55:56
Site Name	840 - Emirates Auctions
Transaction Number	13468691 (CC10009) (CC10025)



Vehicle Details

Chassis Number	5TFDW5F14B*******
Specification	Imported
Make	Toyota
Model	Tundra
Model Year	2011
Color	White
Mileage	138557 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES PORTION GETTING FADED , PORTION RUSTY , PAINT PORTION DAMAGED	الصبغ
01.B Doors	REAR LEFT SIDE PORTION REPAIRED REPAINTED	أبواب
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR CHASSIS MUDDY PORTION MINOR DENT, REAR LEFT SIDE ARCH REPAIRED	الارضية
01.E Bumper	MISALIGN , PARTS COVER MISSING	دعامية
01.F Windshield	FRONT SPOT CRACK	زجاج
01.G Bonnet	SHOCK NOT WORKING	غطاء المحرك
01.H Pillars	LEFT SIDE C/PILLAR OUTER PANEL REPAIRED	القوائم
01.I Trunk	TAIL GATE NOT OPEN , PORTION DENT / LEFT SIDE CABIN RPORTION PORTION REPAIRED REPAIRED	صندوق
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS GETTING RUSTY PORTION MINOR DENT,OK	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	OIL LEAK OPEN REFITTED GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	DRIVER SEAT ADJUSTMENT NOT WORKING	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR OIL LEAK REFITTED GETTING RUSTY,MINOR JERKING	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
05.C Four Wheel Drive	NOT WORKING	الدفع الرباعي
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 WORN OUT CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 WORN OUT CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES , HUB COVER MISSING	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Tail Light	FADED PORTION CRACK	الضوء الخلفي
08 Brake Condition		الفرامل
08.A Hand Brake	NOT WORKING	فرامل اليد
09 Suspension System		ممتص الصدمات
09.A Arms	LOWER ARM BUSHES CUT	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
10 Steering Condition		المقود
10.A Other	GET MAJOT NOISY, HAVE PLY	اخري
11 Interior Condition		الحاله الداخليه
11.A Other	CENTER CONSOLE BOX COVER PORTION DAMAGED , INTERIOR PARTS GETTING RUSTY, SIGN OF FLOODED	اخري
11.B AC Condition	OK , GRILL PANEL PORTION LOOSE	المكيف
11.C Roof Light	FRONT LEFT SIDE COVER LIGHT MISSING , REAR PORTION CRACK	أنارة السقف
11.D Power Window Switch And Glass	FRONT RIGHT SIDE SWITCH NOT WORKING	مفتاح النافذه و الزجاج
11.E Audio	SCREEN DAMAGED , BUTTON PORTION MISSING	صوتيات
11.F Dash Board	WORN OUT ,PORTION CRACK COVER PORTION LOOSE	لوحة القياده
11.G Door Panel	WORN OUT PORTION CRACK	لوحة بطانة الباب
11.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.I Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
12 Battery Condition		حالة البطارية
12.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**