



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>22 Nov 2022, 15:23:17</b>
Transaction Number	<b>64561122 (CC10009)</b>	Queue Number	<b>628066</b>



Chassis Number	<b>JTJHY00W3B4056457</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Lexus</b>
Model	<b>LX 570</b>
Model Year	<b>2011</b>
Color	<b>White</b>
Mileage	<b>331325 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Engine Condition</b>		<b>المحرك</b>
01.A Visual Engine Condition	SIGN OF MINOR OIL LEAK REFITTED	حالة المحرك النظري
01.B Mount	MOUNT RUBBER CRACKED	كرسي
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,	الصبغ
02.B Roof	ROOF & ROOFRAILL REPAIRED REPAINTED	السقف
<b>03 Interior Condition</b>		<b>الحاله الداخليه</b>
03.A AC Condition	OK	المكيف
03.B Roof Ceiling	LOOSE	بطانه السقف
03.C Sunroof	SWITCH PANEL LOOSE	فتحت سقف
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Visual Gear Box Condition	SIGN OIL WET REFITTED	حالة الجير النظري
04.B Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
04.C Road Test	NOT CHECK	فحص علي الطريق
<b>05 Suspension System</b>		<b>ممتص الصدمات</b>

DEFECT	REMARKS	
05.A Arms	LOWER ARM BUSHES CRACKED	ازرع
05.B Other	STABILIZER LINK BOOT CUT	اخري
05.C Ball Joint	BOOT CUT	مفصل كروي
<b>06 Steering Condition</b>		<b>المقود</b>
06.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
<b>07 Tires and Rims Condition</b>		<b>الاطارات</b>
07.A Front Tyre	BOTH SIDE 2021,	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2021,	الاطار الخلفي
<b>08 Lights</b>		<b>الاضاءة</b>
08.A Tail Light	REPLACED	الانارة
<b>09 Chassis Condition</b>		<b>الشاشي</b>
09.A Chassis	OK PORTION MINOR RUSTY	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.