

Queue Number

2877776

Transaction Date

19 Oct 2026, 13:41:47

Site Name

840 - Emirates Auctions

Transaction Number

13170645 (CC10006) (CC10006)



Vehicle Details

Chassis Number	JMYSRCS1A8*****
Specification	GCC Specification
Make	Mitsubishi
Model	Lancer
Model Year	2008
Color	White
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED, DENTS, SCRATCHES, PORTION FADED, PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Bumper	FRONT DAMAGE , REAR MISALIGN PORTION DAMAGE	دعامة
01.D Sign of front accident	FRONT BUMPER FRAME, BULKHEAD, RADIATOR SUPPORT, FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة
01.E Sign of back accident	BACK PANEL, QUATER PANEL, COMPARTMENT REPAIRED	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	FRONT BOTH SIDE CHASSIS & REAR BOTH SIDE EXTENSION REPAIRED , FRONT RIGHT SIDE DAMAGE	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION WORN OUT	حالة المقاعد
---------------------	------------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
07.B Tail Light	BOTH SIDE CRACK	الضوء الخلفي
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	ازرع
08.B Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CRACK	مؤخرة الرودادات
10 Interior Condition		الحالة الداخليه
10.A Other	CENTER CONSOLE BOX COVER WORN OUT, INTERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخرى
10.B AC Condition	NOT CHECK	المكيف
10.C Dash Board	WORN OUT	لوحة القيادة
10.D Roof Ceiling	PORTION WORN OUT	بطانه السقف
10.E Odometer reading	NOT CHECK	قراءة عداد المسافات
10.F Steering Wheel and control buttons	PORTION DAMAGE	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae