CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2949361
Transaction Date	05 Nov 2026, 13:21:57
Site Name	840 - Emirates Auctions
Transaction Number	75305995 (CC10008) (CC10008)



Vehicle Details

Chassis Number	KMHWG81R4F*******
Specification	GCC Specification
Make	Hyundai
Model	H1
Model Year	2015
Color	White
Mileage	341369 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED PORTION REPAIRED,PORTION RUSTY ,PORTION FADED ,DENT,SCRATCHES,PORTION DAMAGED	الصبغ
01.B Doors	PILLAR BEEDING DAMAGED	أبواب
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	PORTION DENT,PORTION RUSTY	الارضية
01.E Bumper	MISALIGN,PORTION DAMAGED	دعامية
01.F Roof	RUSTY	السقف
01.G Fuel Tank	FUEL LEAK	خزان الوقود
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS GETTING RUSTY ,MUDDY	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,OIL LEAK ,REFITTED	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Other	MUFFLER DENT	اخري

Condition	Remarks	الحالة
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	NOT CHECK ,REFITTED	الحالة النظريه للجير
06.B Propeller Shaft	CENTER BEARING RUBBER WORNOUT	ناقل الحركة
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2023 CRACK	الاطار الامامي
07.B Rear Tyre	LEFT SIDE 2023 ,RIGHT SIDE 2020 CRACK	الاطار الخلفي
08 Lights		الاضاءة
08.A Head Light	RIGHT SIDE DAMAGED	الاضاءة الرئيسية
09 Brake Condition		الفرامل
09.A Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
10 Suspension System		ممتص الصدمات
10.A Leaf Spring	GETTING RUSTY ,BUSHES CRACK	
10.B Arms	BUSHES CRACK	ازرع
11 Steering Condition		المقود
11.A Steering Oil	OIL LEAK	زيت المقود
12 Interior Condition		الحاله الداخليه
12.A Other	INTERIOR PARTS RUSTY ,WATER FLOODED	اخري
12.B AC Condition	NOT CHECK	المكيف
12.C Dash Board	PORTION DAMAGED	لوحة القياده
12.D Roof Ceiling	PORTION DAMAGED	بطانه السقف
12.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
12.F Steering Wheel and control buttons	MAJOR WORN OUT	عجلة القيادة وازرار التحكم
12.G Gear Shifting Lever	DUST COVER WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.