CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3001538
Transaction Date	17 Nov 2026, 16:51:50
Site Name	840 - Emirates Auctions
Transaction Number	14094906 (CC10009) (CC10019)



Vehicle Details

Chassis Number	WDDGF4JB9E*******
Specification	GCC Specification
Make	Mercedes
Model	C 200
Model Year	2014
Color	White
Mileage	210940 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	RIGHT SIDE BOTH REPAINTED,PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED,PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Bonnet	REPAINTED,PORTION REPAIRED,REFITTED	غطاء المحرك
01.H Fuel Tank	FUEL WET	خزان الوقود
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	REMOVE ALL UNDER COVERS FOR RECHECK PROPERLY	اخري
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	MINOR OIL LEAK REFITTED SHAKING	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	FRONT BOTH SIDE ADJUSTMENT NOT WORKING PROPERLY, COVER PORTION CRACKED	حالة المقاعد
05 Transmission Condition		**الجير**

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED GETTING RUSTY MINOR JERKING	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Brake Condition		الفرامل
07.A Brake Pedal	GETTING SPONGY	دواسة الفرامل
08 Interior Condition		الحاله الداخليه
08.A Other	TEA CUP SLIIDIN COVER DAMAGED,LOOSE , INNER PARTS RSUTY , SIGN OF WATER FLOODED	اخري
08.B AC Condition	OK	المكيف
08.C Power Window Switch And Glass	SWITCH PORTION FADED	مفتاح النافذه و الزجاج
08.D Roof Ceiling	PORTION LOOSE	بطانه السقف
08.E Door Panel	PORTION CRACKED	لوحة بطانة الباب
08.F Steering Wheel and control buttons	WORN OUT,ADJUSTMENT NOT WORKING PROPERLY	عجلة القيادة وازرار التحكم
08.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae